

MA/11

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8004280475 DOC DATE: 80/04/21 NOTARIZED: NO DOCKET #  
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397  
 AUTH.NAME AUTHOR AFFILIATION  
 RENBERGER,D.L. Washington Public Power Supply System  
 RECIP.NAME RECIPIENT AFFILIATION  
 ENGELKEN,R.H. Region 5, San Francisco, Office of the Director

SUBJECT: Forwards interim deficiency rept re violation of min wall thickness on small bore piping.


DISTRIBUTION CODE: B019B COPIES RECEIVED:LTR 1 ENCL 1 SIZE:L+1  
 TITLE: Construction Deficiency Report (10CFR50.55E)


NOTES:-----


ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	L	T		ID CODE/NAME	L
	14 PM M. LYNCH	1	1	15 BC LWR #4	1	1
	20 LA LWR #4	1	1	21 AD LWR	1	1
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	05 I&E	2	2	07 EDO & STAFF	1	1
	08 MPA	1	1	09 DEPY DIR DPM	1	1
	10 GAB	1	1	11 STANDRDS DEV	1	1
	13 FIELD COOR/IE	1	1	16 AD FOR ENGR	1	1
	17 AD PLANT SYS	1	1	17 AD REAC. SFTY	1	1
	22 DIR DPM	1	1	23 OELD	1	1
	AD/RCI/IE	1	1	AD/SITE TECH	1	1
	AEOD	1	1	DIRECTOR DSE	1	1
	GEOSCIENCES BR	1	1	HANAUER,S.	1	1
	I&C SYS BR	1	1	MATL ENG BR	1	1
	MECH ENG BR	1	1	POWER SYS BR	1	1
	STRUCT ENG BR	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	24 ACRS	16	16			

Ltr  
 MOORE  
 EPB # 2 BC  
 S. KEBLUSEK  
 EPB # 2 LA

APR 29 1980







Washington Public Power Supply System  
A JOINT OPERATING AGENCY

P. O. Box 968 3000 GEO. WASHINGTON WAY RICHLAND, WASHINGTON 99352 PHONE (509) 375-5000

April 21, 1980  
G02-80-93

Nuclear Regulatory Commission

Region V  
Office of Inspection and Enforcement  
Suite 202, Walnut Creek Plaza  
1990 N. California Blvd.  
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2  
DOCKET NO. 50-397, CPPR-93  
REPORTABLE DEFICIENCY 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on March 19, 1980, of a reportable condition regarding the violation of minimum wall thickness on small bore piping.

Attached is our interim report concerning this deficiency. A final report will be scheduled when our design analysis is completed.

Please contact us if you have additional questions.

Very truly yours,

D. L. Renberger  
Assistant Director, Technology

DLR/RTJ/im

Attachment: As stated  
cc: JR Lewis, BPA w/1  
JJ Byrnes, B&R w/1  
V Stello, Director, NRC, WDC w/1  
JJ Verderber, B&R w/1  
WNP2 Files w/1  
LIS-NUS Corporation w/1

3019  
SE  
1/1

5 8004280 475

