

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8009030556 DOC. DATE: 80/08/25 NOTARIZED: NO DOCKET #
 FACIL: STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528-
 STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529
 STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530
 AUTH. NAME: AUTHOR AFFILIATION:
 VAN BRUNT, E.E. Arizona Public Service Co. *mk/1*
 RECIP. NAME: RECIPIENT AFFILIATION:

SUBJECT: Final deficiency rept re undersized structural steel fillet
 welds. Welds are sufficient to handle design loading while
 providing adequate safety margin for crack prevention.
 Dispositioned as not reportable.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL: 1 SIZE: 6 + 30
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Standardized Plant. 05000528
 Standardized Plant. 05000529
 Standardized Plant. 05000530

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	A/D LICENSNG 04	1 1	SCHWENCER, A. 05	1 1
	LEE, J. 06	1 1	KERRIGAN, J. 07	1 1
INTERNAL:	AD/RCI/IE 17	1 1	AEOD 18	1 1
	ASLBP/J. HARD. 1	1 1	D/DIR. HUM. FAC 15	1 1
	DIR, HUM. FAC S10	1 1	EDO & STAFF 19	1 1
	EQUIP. QUALI BR 11	1 1	I&E 09	2 2
	LIC QUAL BR 12	1 1	MPA 20	1 1
	NRC PDR 02	1 1	OELD 21	1 1
	PROC/ISI REV 13	1 1	QA BR 14	1 1
	<u>REG FILE</u> 01	1 1	RUTHERFORD, W. IE	1 1
	STANDRDS DEV 21	1 1		
EXTERNAL:	ACRS 16	16 16	LPDR. 03	1 1
	NSIC 08	1 1		

SEP 1 1980
 - ARPA

TOTAL NUMBER OF COPIES REQUIRED: LTTR 42 ENCL: 42

R

RECEIVED AT THE OFFICE OF THE
DIRECTOR OF THE BUREAU OF
THE ARMY AND NAVAL
COMMISSIONERS OF THE
NAVY DEPARTMENT
WASHINGTON, D. C.
JAN 10 1910

THE SECRETARY OF THE ARMY AND NAVAL
COMMISSIONERS OF THE NAVY DEPARTMENT
WASHINGTON, D. C.
JAN 10 1910

THE SECRETARY OF THE ARMY AND NAVAL
COMMISSIONERS OF THE NAVY DEPARTMENT
WASHINGTON, D. C.
JAN 10 1910

THE SECRETARY OF THE ARMY AND NAVAL
COMMISSIONERS OF THE NAVY DEPARTMENT
WASHINGTON, D. C.
JAN 10 1910

NO.	NAME	DATE	REMARKS
1	JOHN J. ...	...	...
2	...	...	...
3	...	...	...
4	...	...	...
5	...	...	...
6	...	...	...
7	...	...	...
8	...	...	...
9	...	...	...
10	...	...	...
11	...	...	...
12	...	...	...
13	...	...	...
14	...	...	...
15	...	...	...
16	...	...	...
17	...	...	...
18	...	...	...
19	...	...	...
20	...	...	...
21	...	...	...
22	...	...	...
23	...	...	...
24	...	...	...
25	...	...	...
26	...	...	...
27	...	...	...
28	...	...	...
29	...	...	...
30	...	...	...
31	...	...	...
32	...	...	...
33	...	...	...
34	...	...	...
35	...	...	...
36	...	...	...
37	...	...	...
38	...	...	...
39	...	...	...
40	...	...	...
41	...	...	...
42	...	...	...
43	...	...	...
44	...	...	...
45	...	...	...
46	...	...	...
47	...	...	...
48	...	...	...
49	...	...	...
50	...	...	...
51	...	...	...
52	...	...	...
53	...	...	...
54	...	...	...
55	...	...	...
56	...	...	...
57	...	...	...
58	...	...	...
59	...	...	...
60	...	...	...
61	...	...	...
62	...	...	...
63	...	...	...
64	...	...	...
65	...	...	...
66	...	...	...
67	...	...	...
68	...	...	...
69	...	...	...
70	...	...	...
71	...	...	...
72	...	...	...
73	...	...	...
74	...	...	...
75	...	...	...
76	...	...	...
77	...	...	...
78	...	...	...
79	...	...	...
80	...	...	...
81	...	...	...
82	...	...	...
83	...	...	...
84	...	...	...
85	...	...	...
86	...	...	...
87	...	...	...
88	...	...	...
89	...	...	...
90	...	...	...
91	...	...	...
92	...	...	...
93	...	...	...
94	...	...	...
95	...	...	...
96	...	...	...
97	...	...	...
98	...	...	...
99	...	...	...
100	...	...	...

ARIZONA



PUBLIC SERVICE COMPANY

P. O. BOX 21666 • PHOENIX, ARIZONA 85036

August 25, 1980

ANPP-16191-BSK/JAR

U. S. Nuclear Regulatory Commission
Region V
Walnut Creek Plaza - Suite 202
1990 North California Boulevard
Walnut Creek, California 94596

Attention: Mr. G. S. Spencer, Chief
Reactor Construction and
Engineering Support Branch

Subject: A 50.55(e) Potentially Reportable Deficiency
Relating to Undersized Structural Steel Fillet
Welds
Final Report
File: 80-019-026

Reference: (1) Telephone Conversation between R. Haynes
and B. S. Kaplan on June 12, 1980
(DER 80-3)
(2) Interim Report, ANPP-15741, dated June 26,
1980

Dear Sir:

Attached, is our final written report of the potential reportable deficiency, under 10CFR50.55(e), relating to fillet welds for structural steel undersized with respect to AWS D1.1 and AISC minimum weld requirements.

The structural fillet welds referenced in this report, even though undersized with respect to the minimum requirements of AWS D1.1-75 and AISC, are sufficient to handle the design loadings while providing an adequate safety margin for crack prevention. The structural fillet welding referenced herein will be accepted without repair.

Since it is demonstrated that this condition has no safety significance, does not require any repair operations and did not require extensive analysis, it is dispositioned as not reportable.

Very truly yours,

E. E. Van Brunt

E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects
ANPP Project Director

8009030 556

EEVBjr/BSK:skc

Attachments

B019
S
111

Mr. G. S. Spencer, Chief
Reactor Construction and
Engineering Support Branch
ANPP-16191-BSK/JAR
August 25, 1980
Page 2

cc: Victor Stello, Jr., Director w/attachments
~~Office of Inspection and Enforcement~~
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

A. C. Gehr
Snell & Wilmer

J. A. Roedel
R. L. Robb
D. B. Fasnacht
W. E. Ide
J. M. Allen
A. C. Rogers
J. A. Brand
W. H. Wilson
W. G. Bingham
W. J. Stubblefield
J. E. Bashore
R. W. Welcher
D. R. Hawkinson

