



NOVEMBER 17 1986

L-86-469

Dr. J. Nelson Grace
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, N.W., Suite 2900
Atlanta, GA 30323

Dear Dr. Grace:

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335, 50-389
Inspection Report 335/86-20 and 389/86-19

Florida Power & Light Company has reviewed the subject inspection report, and pursuant to the provisions of 10 CFR 2.201 the response is attached.

There is no proprietary information in the report.

Very truly yours,

C. O. Woody
for C. O. Woody
Group Vice President
Nuclear Energy

COW/GRM/gp

Attachment

cc: Harold F. Reis, Esquire

8612030043 861117
PDR ADDCK 05000335
Q PDR



Re: St. Lucie Units 1 and 2
Inspection Report 335/86-20 and 389/86-19
L-86-469

ATTACHMENT

Finding

Unit 2 Technical Specification (TS) 6.8.1.a requires that procedures be established, implemented and maintained for the activities recommended in Appendix "A" of Regulatory Guide 1.33, Revision 2, February 1978.

Appendix "A" of Regulatory Guide 1.33, Revision 2, February 1978, states that the following are typical safety-related activities that should be covered by written procedures: General Plant Operating Procedures on Cold Shutdown to Hot Standby.

Contrary to the above, on August 22, 1986, Operating Procedure (OP) 2-0030121, Rev. 17, Reactor Plant Heat-up Cold to Hot Standby, Appendix C, item 9, was not properly implemented in that electrical breaker 2-41378, containment elevator fan power supply, was in the shut (energized) vice the open position. Additionally, instructions posted on the breaker front require that this breaker be open while at power in accordance with Regulatory Guide 1.63, Electric Penetration Assemblies in Containment Structures for Light-Water-Cooled Nuclear Power Plants.

Response

- 1) FPL concurs with the violation.
- 2) Personnel error was the cause for the finding. The breaker was closed even though a sign on the breaker indicated that it is to be open at power.
- 3) The subject breaker was opened immediately when FPL was notified of the problem.
- 4) FPL reviewed the Regulatory Guide 1.63 commitments and made appropriate changes to existing operating instructions. The oversight of the containment elevator is considered an isolated case and no personnel action is considered necessary.
- 5) Above action was completed on October 17, 1986.