LICENSEE EVENT REPORT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M I D C C 1 2 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5 5 THE REPORT OF THE PROPERTY OF THE P
CON'T 0 1 REPORT L 6 0 5 0 0 0 3 1 5 7 0 3 1 2 7 9 8 0 4 0 3 7 9 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) DURING A ROUTINE SURVEILLANCE TEST IT WAS DISCOVERED THAT THE SPENT FUEL PIT
EXHAUST VENTILATION UNIT FLOW FAILED TO MEET THE ACCEPTANCE CRITERIA IDENTIFIED
O 4 IN T.S. 4.9.12
0 5
0 7
7 8 9 SYSTEM CAUSE CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE SUBCODE
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
LER/RO REPORT VEAR SEQUENTIAL REPORT NO. 17 NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER B 18 X 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 ATTACHMENT FORM SUB. PRIME COMP. COMPONENT MANUFACTURER B 18 X 19 Z 20 Z 21 0 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) THROUGH INVESTIGATION THE CAUSE WAS DETERMINED TO BE THE UNIT'S INTAKE GRILLS
WHICH APPEARED TO HAVE CLOSED SLIGHTLY DUE TO SYSTEM VIBRATION. THE GRILLS
WERE REOPENED AND THE TEST WAS PERFORMED WITH SATISFACTORY RESULTS. TO PREVENT
RECURRENCE, THE GRILL DAMPER LINKAGE WAS SECURELY FASTENED TO PROHIBIT INADVERTANT
MOVEMENT.
7 8 9 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 5 E 28 1 0 0 29 NA B 31 SURVEILLANCE TEST 7 8 ACTIVITY CONTENT 44 45 46 80
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 Z (33) Z (34) NA NA
7 8 9 10 11 44 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 NA 7 8 9 PERSONNEL INJURIES 80
1 8 0 0 0 40 NA
7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 43
1 9 Z 42 NA NA 80
PUBLICITY DESCRIPTION 45 NRC USE ONLY NRC USE ONLY NRC USE ONLY RC USE ONLY RC USE ONLY RC USE ONLY
7 8 9 10 68 69 80 80 80 80 80 80 80 80 80 80 80 80 80

