





100



SUPPLEMENT TO LER#79-018/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

FURTHER INVESTIGATION REVEALED THAT WITH PY-506B IN MANUAL, OPERATION WAS CONSERVATIVE AS LONG AS THE UNIT REMAINED ABOVE 91 PER CENT POWER. POWER LEVELS BETWEEN APRIL 17 AND 23 REMAINED BETWEEN 96 AND 100 PER CENT.

A REVIEW OF T.S. RPS/ESF CIRCUITS WAS PERFORMED TO DETERMINE IF ANY ADDITIONAL CONTROLLERS PROVIDE DIRECT INPUT TO PROTECTIVE FUNCTIONS, THERE WERE NO OTHERS.

TO PREVENT RECURRENCE THE APPROPRIATE STP'S WERE MODIFIED TO PROVIDE A SIGN-OFF TO DOCUMENT SYSTEM RESTORATION.

