


DSB



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

November 26, 1979

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,
the following report/s are submitted:

RO 79-056/03L-0.

Sincerely,

D.V. Shaller
Plant Manager

/bab

- cc: J.E. Dolan
- R.W. Jurgensen
- R.F. Kroeger
- R.W. Kilburn
- R.J. Vollen BPI
- R.E. Masse RO:III
- R.C. Callen MPSC
- P.W. Steketee, Esq.
- R. Walsh, Esq.
- G. Charnoff, Esq.
- G. Olson
- J.M. Hennigan
- PNSRC
- J.F. Stietzel
- E.L. Townley
- Dir., IE (30 copies)
- Dir., MIPC (3 copies)

NOV 28 1979

DUPLICATE

A002
S
1/1

7912040384

30 28 104

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

Licensee Code: M I D C C 1 License Number: 000000000000000000 License Type: 411111 Cat 58

Report Source: L Docket Number: 0500031571027791 Report Date: 112679

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 DURING THE PERFORMANCE OF A SURVEILLANCE TEST PROCEDURE, THE OPENING TORQUE ON TWO OF THE ICE CONDENSER LOWER INLET DOOR (17L AND 21R) EXCEEDED THE MAXIMUM LIMITS AS SPECIFIED IN T.S. 4.6.5.3.1 ITEM 3.

System Code: SA Cause Code: B Cause Subcode: A Component Code: XXXXX Occurrence Code: 03 Report Type: L Valve Subcode: Z

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 IT HAS BEEN FOUND THAT THE SPRINGS USED ON THESE DOORS ARE SLIGHTLY STIFFER THAN THOSE ON THE DOORS IN OTHER BAYS. THE SPRING TENSION ADJUSTMENT BOLTS ON DOORS 17L AND 21R WERE BACKED OUT TO BRING THE OPENING TORQUE TO WITHIN ALLOWABLE VALUES. SEE ATTACHED SUPPLEMENT.

Facility Status: G % Power: 000 Other Status: NA Method of Discovery: B Discovery Description: SURVEILLANCE TEST

Activity Released: Z Amount of Activity: NA Location of Release: NA

Personnel Exposures: 000 Description: NA

Personnel Injuries: 000 Description: NA

Loss of or Damage to Facility: Z Description: NA

Publicity Issued: N Description: NA

SUPPLEMENT TO LER #79-056/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

A DESIGN CHANGE HAS BEEN INITIATED TO REPLACE THE SPRING
ADJUSTMENT BOLTS WITH LONGER BOLTS IN ORDER TO RELIEVE THE
SPRING TENSION ON THE LOWER DOORS, (RFC 12-1762).
THE DOORS WERE IMMEDIATELY READJUSTED WHEN THE PROBLEM WAS
FOUND AND NO ACTION WAS REQUIRED BY TECHNICAL SPECIFICATIONS.

