

November 28, 1989

Docket Nos. 50-315
and 50-316

Mr. Milton P. Alexich, Vice President
Indiana Michigan Power Company
c/o American Electric Power
Service Corporation
1 Riverside Plaza
Columbus, Ohio 43216

Dear Mr. Alexich:

SUBJECT: SUMMARY OF MEETING HELD ON NOVEMBER 8, 1989 WITH AMERICAN ELECTRIC
POWER TO DISCUSS THE D.C. COOK IN-SERVICE TESTING PROGRAM.

On November 8, 1989, the staff met with AEP to readdress relief requests that
were denied in the staff's August 29, 1989 safety evaluation (SE). Meeting
attendees are listed in Enclosure 1. Slides used during the presentation (all
non-proprietary) are provided as Enclosure 2.

AEP discussed those recommendations of the safety evaluation which they are
planning to adopt and provided technical justification and clarification for
the remaining issues in the safety evaluation. Resolution of the SE issues is
discussed in the enclosed supplemental safety evaluation (Enclosure 3).

The staff requested that AEP resubmit their modified IST program by February 16,
1990 so that an approved program can be in place by April 1, 1990.

Sincerely,

Original signed by

Joseph G. Gitter, Project Manager
Project Directorate III-1
Division of Reactor Projects - III,
IV, V & Special Projects
Office of Nuclear Reactor Regulation

DISTRIBUTION

~~DOCKET FILE~~


NRC & LOCAL PDRs
PD31 GRAY FILE
JSNIEZEK
JTHOMA
JGIITTER
OGC
EJORDAN
ACRS(10)
JCLIFFORD
BJORGENSEN, SRI
BRUCE BURGESS, RIII

*See previous concurrence

**PM/PD31:DRSP
JGIITTER
11/22/89


(A)P/PD31:DRSP
JTHOMA
11/28/89

*EMEB
LMARSH
11/22/89

QFol
11


COOK IST MTG

8912070372 891128
PDR ADDCK 05000315
P PNU



Faint, illegible text scattered across the middle section of the page, possibly representing a list or a series of entries.

A small, faint block of text located in the lower-left quadrant of the page.

A small, faint block of text located in the lower-right quadrant of the page.

Docket Nos. 50-315
and 50-316

Mr. Milton P. Alexich, Vice President
Indiana Michigan Power Company
c/o American Electric Power
Service Corporation
1 Riverside Plaza
Columbus, Ohio 43216

Dear Mr. Alexich:

SUBJECT: SUMMARY OF MEETING HELD ON NOVEMBER 8, 1989 WITH AMERICAN ELECTRIC
POWER TO DISCUSS THE D.C. COOK IN-SERVICE TESTING PROGRAM.

On November 8, 1989, the staff met with AEP to readdress relief requests that were denied in the staff's August 29, 1989 safety evaluation (SE). Meeting attendees are listed in Enclosure 1. Slides used during the presentation (all non-proprietary) are provided as Enclosure 2.

AEP discussed those recommendations of the safety evaluation which they are planning to adopt and provided technical justification and clarification for the remaining issues in the safety evaluation. Resolution of the SE issues is discussed in the enclosed supplemental safety evaluation (Enclosure 3).

The staff requested that AEP resubmit their modified IST program by February 16, 1990 so that an approved program can be in place by April 1, 1990.

Sincerely,

John F. Stang, Project Manager
Project Directorate III-1
Division of Reactor Projects - III,
IV, V & Special Projects
Office of Nuclear Reactor Regulation

DISTRIBUTION
DOCKET FILE
NRC & LOCAL PDRs
PD31 GRAY FILE
JSNIEZEK
JTHOMA
JGIITTER
OGC
EJORDAN
ACRS(10)
JCLIFFORD

PM/PD31:DRSP
JGIITTER
11/22/89

(A)D/PD31:DRSP
JTHOMA
11/ /89

EGS
for
EMEB
LMARSH
11/22/89

w/ comments

COOK IST MTG



10

[The body of the document contains extremely faint and illegible text, likely bleed-through from the reverse side of the page. The text is scattered across the page and cannot be transcribed accurately.]



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

November 28, 1989

Docket Nos. 50-315
and 50-316

Mr. Milton P. Alexich, Vice President
Indiana Michigan Power Company
c/o American Electric Power
Service Corporation
1 Riverside Plaza
Columbus, Ohio 43216

Dear Mr. Alexich:

SUBJECT: SUMMARY OF MEETING HELD ON NOVEMBER 8, 1989 WITH AMERICAN ELECTRIC
POWER TO DISCUSS THE D.C. COOK IN-SERVICE TESTING PROGRAM.

On November 8, 1989, the staff met with AEP to readdress relief requests that were denied in the staff's August 29, 1989 safety evaluation (SE). Meeting attendees are listed in Enclosure 1. Slides used during the presentation (all non-proprietary) are provided as Enclosure 2.

AEP discussed those recommendations of the safety evaluation which they are planning to adopt and provided technical justification and clarification for the remaining issues in the safety evaluation. Resolution of the SE issues is discussed in the enclosed supplemental safety evaluation (Enclosure 3).

The staff requested that AEP resubmit their modified IST program by February 16, 1990 so that an approved program can be in place by April 1, 1990.

Sincerely,

Joseph G. Gitter

Joseph G. Gitter, Project Manager
Project Directorate III-1
Division of Reactor Projects - III,
IV, V & Special Projects
Office of Nuclear Reactor Regulation

Mr. Milton Alexich
Indiana Michigan Power Company

Donald C. Cook Nuclear Plant

cc:
Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Mr. S. Brewer
American Electric Power
Service Corporation
1 Riverside Plaza
Columbus, Ohio 43216

Attorney General
Department of Attorney General
525 West Ottawa Street
Lansing, Michigan 48913

Township Supervisor
Lake Township Hall
Post Office Box 818
Bridgman, Michigan 49106

Al Blind, Plant Manager
Donald C. Cook Nuclear Plant
Post Office Box 458
Bridgman, Michigan 49106

U.S. Nuclear Regulatory Commission
Resident Inspectors Office
7700 Red Arrow Highway
Stevensville, Michigan 49127

Gerald Charnoff, Esquire
Shaw, Pittman, Potts and Trowbridge
2300 N Street, N.W.
Washington, DC 20037

Mayor, City of Bridgman
Post Office Box 366
Bridgman, Michigan 49106

Special Assistant to the Governor
Room 1 - State Capitol
Lansing, Michigan 48909

Nuclear Facilities and Environmental
Monitoring Section Office
Division of Radiological Health
Department of Public Health
3500 N. Logan Street
Post Office Box 30035
Lansing, Michigan 48909

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

ENCLOSURE 1

<u>NAME</u>	<u>TITLE</u>	<u>ORGANIZATION</u>
Steve Brewer	Manager, NS & L	AEPSC
Edward V. Gilabert	Engineer, Tech Support	AEPSC
Dilip Vadodaria	Piping & Valves Nuclear Engineering	AEPSC
Thaddeus R. Stephens	Production Supervising Engineer	D C COOK
Jeff St. Amand	Mechanical Performance Supervisor	D C COOK
Byron Bradley	Tech Eng - IST Perf Eng	D C COOK
Donna J. Moeller	NS & L Nuclear Engineer III	AEPSC
John Huang	MEB	NRR
Joseph G. Gitter	Project Manager	NRR/NRC
Ted Sullivan	Section Chief, EMEB	NRC/NRR/EMEB

**SER FOR DONALD C. COOK NUCLEAR PLANT
INSERVICE TESTING (IST) FOR
PUMPS AND VALVES**

- o SER ISSUES NO LONGER IN CONTENTION**

- o APPENDIX C OF SER**
 - INCLUDING GL 89-04 DISCUSSION**

- o ADDITIONAL TECHNICAL JUSTIFICATION
FOR SER ISSUES STILL IN CONTENTION**

ISSUES NO LONGER IN CONTENTION

**PP-31N AND -31S - SPENT FUEL PIT COOLING
PUMPS**

ISSUE

DENIED RELIEF FROM THE FLOW MEASUREMENTS

- COMPLY WITH THE SER**
- INSTALL INSTRUMENTATION**

**TENTATIVE COMPLETION DATE
JANUARY 31, 1990**

ISSUES NO LONGER IN CONTENTION

**MS-108-2 AND -108-3 - MAIN STEAM-TO-
TDAFP CHECK VALVE**

ISSUE

o CONDITIONALLY GRANTED RELIEF

- VALVE CLOSURE VERIFIED BY
DISASSEMBLY IN ACCORDANCE WITH
GL 89-04**

**NOTE: FULL STROKE TO THE OPEN POSITION
ON A COLD SHUTDOWN FREQUENCY**

- PROGRAM NOTE REVISION**


ISSUES NO LONGER IN CONTENTION

ESW-109 (145), -115 (240), AND -243

ISSUE

**DENIED RELIEF REQUESTED FROM THE
REQUIREMENT TO QUARTERLY EXERCISE THE
VALVES TO THE OPEN POSITION**

- TEST ON A COLD SHUTDOWN FREQUENCY**
- PROGRAM NOTE REVISION**



APPENDIX C

1) IDENTIFY NOTES AS COLD SHUTDOWN JUSTIFICATION OR RELIEF REQUEST

- REVISION TO PROGRAM NOTES

NOTE

FW-134 AND FW-135 (COLD SHUTDOWN JUSTIFICATION):

THESE VALVES ARE LOCATED ON THE SUCTION AND DISCHARGE LINES OF THE TURBINE DRIVEN AUXILIARY FEEDPUMP. THE MAXIMUM FLOW RATE THROUGH THE TURBINE DRIVEN AUXILIARY FEEDPUMP DURING IST IS APPROXIMATELY 700 GPM USING THE PUMP TEST LINE. PASSING THE DESIGN FLOW OF 900 GPM THROUGH THESE VALVES WOULD REQUIRE DELIVERING COLD AUXILIARY FEEDWATER WATER TO THE STEAM GENERATORS. THIS WOULD RESULT IN THERMAL SHOCK TO THE STEAM GENERATOR NOZZLES. THEREFORE, THESE VALVES WILL BE PART STROKE EXERCISED QUARTERLY AND FULL STROKE EXERCISED (PASSING DESIGN FLOW OF 900 GPM THROUGH THE VALVES) AT A COLD SHUTDOWN FREQUENCY.

APPENDIX C

2) FAST ACTING VALVES

- REVISION TO PROGRAM - MAXIMUM
LIMITING STROKE TIMES OF UP TO TWO
SECONDS**

APPENDIX C

**3) TESTING BY DISASSEMBLY -
GL 89-04**

- PROPOSED CHANGE TO PROGRAM

NOTE

THE RELIEF REQUEST NOTES WILL INDICATE WHEN ALTERNATIVE TESTING IS TO BE PERFORMED ON A CHECK VALVE PER GL 89-04, ITEM #2, IN LIEU OF THE STROKE TESTING REQUIRED BY SECTION XI, PARAGRAPH IWV 3521.

ALTERNATIVE TESTING WILL BE ACCOMPLISHED BY DISASSEMBLY OR RADIOGRAPHY DURING REFUELING OUTAGES. THESE METHODS ARE EXPLAINED BELOW:

- (A) DISASSEMBLY METHOD - THE VALVE BONNET WILL BE REMOVED, THE DISC MANUALLY FULL STROKE EXERCISED AND THE VALVE INTERNALS VISUALLY INSPECTED PER GL 89-04. THE RESULTS OF THIS TEST WILL BE DOCUMENTED.

- (B) RADIOGRAPHY METHOD - THIS METHOD WILL BE USED AS AN ALTERNATIVE TESTING METHOD TO DETERMINE THE DISC POSITION UNDER NO FLOW OR REVERSE FLOW CONDITIONS (I.E., VALVE SEATED). THIS, IN CONJUNCTION WITH THE FULL FORWARD FLOW TESTING OF THE VALVE, CAN PROVIDE ASSURANCE THAT THE DISC IS FREE TO MOVE FROM FULL OPEN POSITION DURING FORWARD FLOW TO THE CLOSED POSITION WITH NO FLOW OR REVERSE FLOW CONDITIONS. THE RESULTS OF THIS TEST WILL BE DOCUMENTED.



APPENDIX C

4) FW-118-1, -2, -3, AND -4
DISCUSSED LATER

5) FW-134 AND -135 FULL FLOW TESTING

- PART STROKE QUARTERLY

- FULL STROKE TEST ON A COLD SHUTDOWN
FREQUENCY

APPENDIX C

6) CONTAINMENT ISOLATION VALVE TESTING

- DOCUMENT IN THE IST PROGRAM

7), 8) AND 9)

DISCUSSED LATER

APPENDIX C

10) NOTE 6 FOR SI-161

- DISCREPANCY WILL BE CORRECTED

11) RH-108E AND -108W

DISCUSSED LATER



32

APPENDIX C

12) XRV-221 AND -222

- NO REQUIRED FAIL SAFE POSITION

13) CRV-470

DISCUSSED LATER

14) ESW-109(145), -114(240) AND -243

DISCUSSED EARLIER

15) IMO-330, -331, -340 AND -350

- INCLUDE RELIEF REQUEST

APPENDIX C

16) ESW-111(141), -112(142), -113(143),
AND -114(144)

NO RELIEF REQUEST REQUIRED

- ALL REQUIRED TESTS FOR SECTION XI
ARE PERFORMED

- NOTE ON DISASSEMBLY

RESPONSE TO IE BULLETIN 83-03

17) SPENT FUEL PIT COOLING PUMP FLOW
MEASUREMENTS

DISCUSSED EARLIER

ISSUES STILL IN CONTENTION

FW-118-1, -2, -3, AND -4

FEEDWATER HEADER CHECK VALVES:

ISSUE

**DENIED RELIEF REQUESTED FROM
QUARTERLY EXERCISING TO THE CLOSED
POSITION**

ADDITIONAL JUSTIFICATION

**ALTERNATE TEST METHOD - DISASSEMBLY
ON REFUELING OUTAGE FREQUENCY**

- NO POSITION INDICATORS**
- NOT-POSITIVE BACKSEAT VALVES**

**AT COLD SHUTDOWN - DISASSEMBLY
COULD DELAY RETURN TO POWER**

- DRAINING THE SG FEEDWATER HEADER**
- MANUALLY LIFTING VALVE BONNET**
- WHIP RESTRAINT DISASSEMBLY**
- HEAVY, LARGE COMPONENT**

ISSUES STILL IN CONTENTION

QRV-200 AND -251

NORMAL CHARGING CONTROL VALVES

ISSUE

DENIED RELIEF REQUESTED FROM FAIL
SAFE TESTING AND STROKE TIMING
REQUIREMENTS

ADDITIONAL JUSTIFICATION

STROKE TIMING

- NO LOCAL OR REMOTE POSITION
INDICATOR

FAIL SAFE POSITION

- QRV-200 - NONE REQUIRED
- QRV-251 - FAIL OPEN
- DISASSEMBLE THE AIR SUPPLY LINE

ISSUES STILL IN CONTENTION

**CRV-470 - LETDOWN HEAT EXCHANGER
TEMPERATURE CONTROL VALVE**

ISSUE


**DENIED RELIEF REQUESTED FROM FAIL
SAFE TESTING**

ADDITIONAL JUSTIFICATION

**FAIL SAFE TEST AT POWER TO CLOSE
POSITION IMPRACTICAL**

- WITH LETDOWN OUT OF SERVICE
 - PRESSURIZER LEVEL CONTROL CONCERNS
- WITH LETDOWN IN SERVICE
 - HIGH TEMPERATURE, WHICH CAUSES
 - FLASHING CAUSING POTENTIAL WATER HAMMER DAMAGE
 - LIFTING OF THE LETDOWN LINE SAFETY VALVES

**FAIL SAFE TEST ON A COLD SHUTDOWN
FREQUENCY**



ISSUES STILL IN CONTENTION

SI-189

CONTAINMENT ISOLATION CHECK VALVE

ISSUE

**DENIED RELIEF REQUESTED FROM
EXERCISING VALVE TO OPEN POSITION**

ADDITIONAL JUSTIFICATION

**FULL STROKE ONLY POSSIBLE BY VALVE
DISASSEMBLY**

- FULL FLOW IS APPROXIMATELY 800 GPM**
- 3/4-INCH TEST CONNECTION**
- VALVE LOCATED INSIDE CONTAINMENT**

**PART STROKE TEST ON A COLD SHUTDOWN
FREQUENCY**

**FULL STROKE VERIFIED BY VALVE
DISASSEMBLY ON A REFUELING OUTAGE
FREQUENCY**

ISSUES STILL IN CONTENTION

RH-108E AND -108W

RHR PUMP DISCHARGE LINE CHECK VALVES

ISSUE

**DENIED REQUEST TO TEST ON A COLD
SHUTDOWN FREQUENCY**

ADDITIONAL JUSTIFICATION

**FULL STROKE AT POWER OPERATION NOT
DESIRABLE**

- DESIGN MODIFICATION TO EXISTING
INSTRUMENTATION (0-1500 GPM)
DESIGN FLOW 3000 GPM**
- TWO-LOOP INJECTION CONFIGURATION**

PART STROKE QUARTERLY

FULL STROKE ON A COLD SHUTDOWN FREQUENCY

ISSUES STILL IN CONTENTION

NSO-021, -022, -023 AND -024

REACTOR HEAD VENT VALVES

NSO-061, -062, -063 AND -064

PRESSURIZER VENT VALVES

ISSUE

**DENIED RELIEF REQUESTED FROM
REFUELING FREQUENCY, EXERCISING,
STROKE TIMING, AND FAIL-SAFE
TESTING REQUIREMENTS**

ADDITIONAL JUSTIFICATION

**PERFORM TESTING ON A COLD SHUTDOWN
FREQUENCY WHEN RCS PRESSURE LESS THAN
OR EQUAL TO 80 LBS**