

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9904290045 DOC.DATE: 99/04/16 NOTARIZED: NO DOCKET #
FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315
AUTH.NAME . AUTHOR AFFILIATION
RENCHECK,M.W. Indiana Michigan Power Co.
RECIP.NAME RECIPIENT AFFILIATION
Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-006-00, "Fuel Crane Loads Lifted Over SFP
Could Impack Energies Greater Than TS Limits," IAW
10CFR50.73.Submittal was delayed to allow for resolution of
questions.Commitment made by licensee,listed.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 2+1
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	LPD3-1 PD	1 1	STANG,J	1 1
INTERNAL:	AEOD/SPD/RRAB	1 1	<u>FILE CENTER</u>	1 1
	NRR/DIPM/IOLB	1 1	NRR/DIPM/IQMB	1 1
	NRR/DRIP/REXB	1 1	NRR/DSSA/SPLB	1 1
	RES/DET/EIB	1 1	RGN3 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LMITCO MARSHALL	1 1
	NOAC POORE,W.	1 1	NOAC QUEENER,DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTR
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL 16

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Plant
Bridgman, MI 49106
616 465 5901



April 16, 1999

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

Operating License DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following report is being submitted:

LER 315/99-006-00, "Fuel Crane Loads Lifted Over Spent Fuel Pool Could Impact Impact Energies Greater than Technical Specification Limits"

The following commitment has been identified in this submittal:

- The root cause investigation for this event has not been completed. Based on the results of this investigation, information regarding the safety significance of this condition, including additional corrective and preventive actions, will be provided in an update to this LER upon completion of the investigation.

This LER was originally due to be submitted on March 23, 1999. Due to uncertainty as to technical issues that directly affect the reportability of this event, submittal of the LER was delayed to allow for resolution of questions. It is recognized that the submittal of this document exceeds the 30 day requirement of 10 CFR 50.73. A Condition Report has been written and entered into the corrective action program to address this issue.

Sincerely,

M. W. Rencheck
Vice President - Nuclear Engineering

/mbd
Attachment

9904290045 990416
PDR ADDCK 05000315
S PDR

0.004

Teru

c: J. E. Dyer, Region III
P. A. Barrett
D. F. Kunsemiller
R. . Whale
D. Hahn
Records Center, INPO
NRC Resident Inspector