

· REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9906220197 DOCKET # DOC.DATE: 99/06/18 NOTARIZED: NO FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315 AUTH.NAME AUTHOR AFFILIATION Indiana Michigan Power Co. (formerly Indiana & Michigan Ele BAKKEN, A.C. RECIP.NAME RECIPIENT AFFILIATION Records Management Branch (Document Control Desk) SUBJECT: Forwards LER 99-014-00 re requirement of TS 4.0.5 not met for Boron injection tank bolting. Commitments identified in submittal listed. DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR ENCL SIZE: TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc. NOTES:

A

T

E

D

TT

M

N

	RECIPIENT	COPI	-	RECIPIENT ID CODE/NAME STANG, J	COPIES		G
	ID CODE/NAME LPD3-1 PD	LTTF 1	R ENCL 1		LTTR 1	ENCL 1	0
INTERNAL:	AEOD/SPD/RRAB	1	1	FILE CENTER	1	1	R
	NRR/DIPM/IOLB	1	1	NRR/DIPM/IQMB	1	1	**
	NRR/DRIP/REXB	1	1	NRR/DSSA/SPLB	1	1	Y
	RES/DET/EIB	1	1	RGN3 FILE 01	1	, 1 ,	
EXTERNAL:	L ST LOBBY WARD	1	1	LMITCO MARSHALL	1	1	1
	NOAC POORE, W.	1	1	NOAC QUEENER, DS	1	1	
u	NRC PDR	1	, 1 *	NUDOCS FULL TXT	, 1 ,	1	-

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 16 ENCL 16

Indiana Michigan Power Company Cook Nuclear Plant One Cook Plant Bridgman, MI 49106 616 465 5901



June 18, 1999

United States Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Operating License DPR-58 Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10CFR50.73(a)(2)(i)(B) the following report is being submitted:

LER 315/99-014-00, "Requirements of Technical Specification 4.0.5 Not Met for Boron Injection Tank Bolting".

The following commitments were identified in this submittal:

- The Boron Injection Tanks (BIT) bolting has been administratively placed in the ISI database for the third ISI interval. Examination of the bolts has been scheduled and will be performed prior to Mode 4.
- Engineering has developed an action plan to review the ISI Program for compliance with all regulatory requirements prior to restart.
- A lesson learned will be placed in the program notebook to alert personnel of the previously missed examinations.
- PMI-5070, Inservice Inspection, will be revised to require that ISI Program changes will be reviewed in accordance with the requirements of 10 CFR 50.59.

2.03

Sincerely,

A. Christopher Bakken, III

Site Vice President

/mbd Attachment

c: J. E. Dyer, Region III

R. P. Powers

P. A. Barrett

D. F. Kunsemiller

R. Whale

D. Hahn

Records Center, INPO

NRC Resident Inspector

407 050410

9906220197 990618 PDR ADDCK 05000315 JE22