

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9908100138      DOC.DATE: 99/08/04      NOTARIZED: NO      DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana M 05000315  
 AUTH.NAME      AUTHOR AFFILIATION  
 BAKKEN, A.C.      Indiana Michigan Power Co.  
 RECIP.NAME      RECIPIENT AFFILIATION  
                      Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-029-01, "Fuel Handling Ventilation Sys  
 Inoperable Due to Original Design Deficiency." Supplemental  
 rept represents extensive rev to original LER & replaces  
 rept entirely. Commitment made by licensee, listed.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 1 + 4  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL
	LPD3-1 PD		1	1	STANG, J		1	1
INTERNAL:	FILE CENTER		1	1	NRR/DIPM/IOLB		1	1
	NRR/DRIP/REXB		1	1	NRR/DSSA/SPLB		1	1
	RES/DET/ERAB		1	1	RES/DRAA/OERAB		1	1
	RGN3 FILE 01		1	1				
EXTERNAL:	L ST LOBBY WARD		1	1	LIMITCO MARSHALL		1	1
	NOAC POORE, W.		1	1	NOAC QUEENER, DS		1	1
	NRC PDR		1	1	NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIS:  
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTR:  
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTR 15 ENCL 15

Indiana Michigan  
Power Company  
Cook Nuclear Plant  
One Cook Plant  
Bridgman, MI 49106  
616 465 5901



August 4, 1999

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Operating License DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73 entitled Licensee Event Report System, the following supplemental report is being submitted:

LER 315/98-029-01, "Fuel Handling Area Ventilation System Inoperable Due to Original Design Deficiency". This supplemental report represents an extensive revision to the original LER and replaces that report in its entirety.

The following commitment was identified in this LER.

- The radiological analysis for the Spent Fuel Handling Accidents in the Auxiliary Building is being redone and is scheduled to be completed by August 30, 1999.

Sincerely,

A. Christopher Bakken III

Site Vice President

/lrb  
Attachment

c: J. E. Dyer, Region III  
R. P. Powers  
P. A. Barrett  
G. P. Arent  
R. Whale  
D. Hahn  
Records Center, INPO  
NRC Resident Inspector

*Test*

9908100138 990804  
PDR ADOCK 05000315  
S PDR