

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | I | D | C | C | L | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | 5

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 5 | 7 | 0 | 9 | 2 | 9 | 7 | 9 | 8 | 1 | 0 | 2 | 9 | 7 | 9 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | DURING A SURVEILLANCE TEST THE GLYCOL CONTAINMENT ISOLATION VALVES
0 3 | VCR-10 AND 20 WOULD NOT CLOSE. THESE VALVES WERE DETERMINED INOPERABLE
0 4 | IN RESPECT TO T.S. 3.6.3.1. THE ACTION REQUIREMENTS WERE MET AS
0 5 | THESE VALVES WERE DECLARED OPERABLE IN LESS THAN FOUR (4) HOURS.
0 6 |
0 7 |
0 8 |

0 9 | SYSTEM CODE: S D (11) | CAUSE CODE: X (12) | CAUSE SUBCODE: Z (13) | COMPONENT CODE: V A L V E X (14) | COMP. SUBCODE: D (15) | VALVE SUBCODE: D (16)
17 | LER/RO REPORT NUMBER: 7 9 | EVENT YEAR: 7 9 | SEQUENTIAL REPORT NO.: 0 5 1 | OCCURRENCE CODE: 0 3 | REPORT TYPE: L | REVISION NO.: 0
ACTION TAKEN: X (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS: 0 0 0 0 (22) | ATTACHMENT SUBMITTED: Y (23) | NPRD-4 FORM SUB.: N (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER: G 2 5 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | WHEN ATTEMPTING TO CLOSE VCR-10 AND 20 VALVE INDICATION SHOWED THAT
1 1 | THESE VALVES WERE STILL OPEN. A VISUAL CHECK OF VCR-10 AND 20
1 2 | REVEALED THAT THEY WERE FULLY OPEN. DURING THIS INSPECTION THESE
1 3 | VALVES CLOSED PARTIALLY. BY CYCLING THESE VALVES THEY BEGAN TO
1 4 | OPERATE PROPERLY, OPENING AND CLOSING FULLY. SEE SUPPLEMENT.

1 5 | FACILITY STATUS: E (28) | % POWER: 1 0 0 (29) | OTHER STATUS: NA (30) | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION: SURVEILLANCE TEST (32)

1 6 | ACTIVITY CONTENT RELEASED: Z (33) | AMOUNT OF ACTIVITY: NA (35) | LOCATION OF RELEASE: NA (36)

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION: NA (39)

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 (40) | DESCRIPTION: NA (41)

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) | DESCRIPTION: NA (43) | PUBLICITY ISSUED: N (44) | DESCRIPTION: NA (45)

7911020389

2 0 | NAME OF PREPARER: J. L. Rischling | PHONE: 616-465-5901

SUPPLEMENT TO LER #79-051/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THESE VALVES WERE THEN REPEATEDLY STROKED TO SEE IF THE PROBLEM WOULD RECUR. NO FURTHER PROBLEMS WERE ENCOUNTERED WITH THESE VALVES AND THEY WERE DECLARED OPERABLE. DURING THIS EVENT THE INNER CONTAINMENT ISOLATION VALVES FOR THESE PENETRATIONS WERE OPERABLE. SINCE THIS IS THE FIRST SUCH PROBLEM ENCOUNTERED WITH THESE VALVES, NO FURTHER ACTION IS PLANNED AT THIS TIME.

