

## CENSEE EVENT REPORT

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

CON'T

0	1	REPORT SOURCE	L	6	0	5	0	0	0	3	1	5	7	1	0	0	1	7	9	8	1	0	3	0	7	9	9		
7	8		60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | DURING THE INVESTIGATION OF A HIGH LEVEL INDICATION FOR NUMBER  
0 3 | FOUR (4) STEAM GENERATOR, TRANSMITTER BLP-142 WAS FOUND TO HAVE  
0 4 | DRIFTED 7 PER CENT HIGH. THIS CONDITION WAS NON CONSERVATIVE  
0 5 | WITH RESPECT TO T.S. TABLE 3.3-1 ITEMS 14 AND 15.  
0 6 |  
0 7 |  
0 8 |

SYSTEM CODE I A (11)		CAUSE CODE E (12)		CAUSE SUBCODE E (13)		COMPONENT CODE I N S T R U (14)				COMP. SUBCODE T (15)		VALVE SUBCODE Z (16)	
LER/RO REPORT NUMBER 7 9 (17)		EVENT YEAR 7 9 (21 22)		SEQUENTIAL REPORT NO. 0 5 2 (24 25 26)		OCCURRENCE CODE 0 3 (28 29)		REPORT TYPE L (30)		REVISION NO. (32)			
ACTION TAKEN E (18)		FUTURE ACTION X (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 (22 23 24)		ATTACHMENT SUBMITTED Y (25)		NPRD-4 FORM SUB. Y (26)	
PRIME COMP. SUPPLIER A (27)		COMPONENT MANUFACTURER B 0 8 0 (28 29 30 31)											

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE TRANSMITTER, BLP-142, WAS RECALIBRATED TO THE PROPER SPECIFICATION  
1 1 AND THEN PLACED BACK IN OPERATION. THE TRANSMITTER HAS SHOWN NO  
1 2 DRIFTING SINCE THE INITIAL SHIFT. THIS PROBLEM HAS BEEN BROUGHT  
1 3 TO THE ATTENTION OF THE MANUFACTURER AND WE ARE WAITING FOR A  
1 4 REPLY FROM THEM. SEE SUPPLEMENT.

8 9  
FACILITY STATUS (28) 1 5 E 9 10 % POWER 1 0 0 12 13 OTHER STATUS (30) NA 44  
7 8 9 10 11 12 13 14  
ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA 44  
7 8 9 10 11 12 13 14  
PERSONNEL EXPOSURES  
NUMBER TYPE Z (37) (38) DESCRIPTION NA (39) 80  
7 8 9 10 11 12 13 14  
PERSONNEL INJURIES  
NUMBER DESCRIPTION (40) NA 80  
7 8 9 10 11 12 13 14  
LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION NA 80  
7 8 9 10 11 12 13 14  
PUBLICITY (45)  
ISSUED DESCRIPTION (44) NA 80  
7 8 9 10 11 12 13 14  
METHOD OF DISCOVERY (31) A 45 46 OPERATOR DISCOVERY DESCRIPTION (32) 80  
LOCATION OF RELEASE (36) NA 80  
7911070488  
NRC USE ONLY  
68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER S. D. DeLong

PHONE: 616-465-5901



SUPPLEMENT TO LER #79-052/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THIS INVESTIGATION WILL REMAIN OPEN AND IF A DEFINITE CAUSE  
IS DETERMINED A SUPPLEMENTAL LER WILL BE SUBMITTED.  
THE ACTION ITEM REQUIREMENT OF TABLE 3.3-1 FOR ITEMS 14  
AND 15 WAS FULFILLED.