



SUPPLEMENT TO LER #79-002/03X-1

SUPPLEMENT TO CAUSE DESCRIPTION

OFFSET TO WITHIN THE TARGET BAND.

THE PROBLEM WITH THE ANNUNCIATOR FAILING TO COME IN IS BELIEVED
TO HAVE BEEN AN INTERMITTENT HARDWARE FAILURE. EXTENSIVE TESTS
HAVE BEEN RUN ON THE P250 DELTA FLUX ALARM AND THE ALARM ANNUNCIATOR
FUNCTIONED CORRECTLY. NO FURTHER ACTION IS PLANNED.

