



SUPPLEMENT TO LER # 79-042/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THE INVERTER WAS SWITCHED TO AN ALTERNATE POWER SUPPLY UNTIL THE FUSE WAS REPLACED. THE INVERTER WAS THEN SWITCHED BACK TO ITS NORMAL POWER SUPPLY. TO PREVENT RECURRENCE, THE CONTRACTOR PERSONNEL WERE GIVEN ADDITIONAL TRAINING ON NOVEMBER 08, 1979 WHICH REVIEWED THE REQUIREMENTS FOR WORKING IN CRITICAL AREAS ON SAFETY RELATED EQUIPMENT. PARTICULARLY REQUIREMENTS FOR CABLE REMOVAL AND WORK AUTHORIZATIONS.