





50

SUPPLEMENT TO LER # 79-062/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

FURTHER INVESTIGATION REVEALED THAT CHANNEL I WAS INFACIT THE INOPERABLE CHANNEL AND IT WAS PLACED BACK IN TRIP WITH CHANNEL II RETURNED TO NORMAL.

THE NAME PLATES FOR PANEL INDICATORS WERE CORRECTED AND THE NAME PLATES FOR THE OTHER STEAM FLOW CHANNELS, IN BOTH UNITS WERE VERIFIED.

A DESIGN CHANGE HAS BEEN INITIATED WHICH WILL IMPROVE THE CONSISTENCY OF AEP LABELING FOR THE STEAM FLOW CHANNELS AND ELIMINATE ANY CONFUSION IN LABELING. THE ACTION REQUIREMENTS OF T.S. TABLES 3.3-1 AND 3.3-3 WERE FULFILLED.