

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8101050356 DOC. DATE: 80/12/16 NOTARIZED: NO DOCKET #
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 SHALLER, D.V. Indiana & Michigan Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 KEPPLER, J.G. Region 3, Chicago, Office of the Director

SUBJECT: RO: on 801215 spray header isolation valves CTS-124E &
 CTS-128E were discovered sealed & locked closed at 9:30-h.
 Valves reopened relocked & resealed in correct position.
 Followup rept will be submitted by 801226.

DISTRIBUTION CODE: M007S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: LER (Backfit)

NOTES: Send 3 copies of all material to I&E. 05000316


	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL		ID	CODE/NAME	LTTR	ENCL
INTERNAL:	AEOD		2			ASLBP/J.HARD	1		
	I&E	04	2			MPA	1		
	NRG PDR	02	1			OP EX EVAL BR	1		
	<u>REG FILE</u>	01	1						
EXTERNAL:	LPDR	03	1			NSIC	1		

JAN 6 1981

As 4

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 0

IF





INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

1981 JAN 2 PM 3 31
DISTRICT OF COLUMBIA
REGULATORY SERVICES UNIT
US NRC
DISTRICT BRANCH
REGULATORY SERVICES

December 16, 1980

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm our verbal report to NRC Region III Inspector, Mr. E. Swanson, at 0930 hours on December 15, 1980. At that time we reported that during a tour being performed by a plant Auxiliary Equipment Operator, it was discovered that two spray header isolation valves (CTS-124E and CTS-128E), located in the Unit 2 East Containment Heat Exchanger Room, were sealed and locked closed. This condition was immediately reported to the Shift Operating Engineer who determined that the as found condition was incorrect. Instructions were given to immediately reopen the valves and relock and reseal them in the correct position.

A written followup report will be submitted by December 26, 1980, as required by Technical Specification Section 6.9.1.8.

Sincerely,

D.V. Shaller
Plant Manager

/bab

- cc: J.E. Dolan
- R.S. Hunter
- R.W. Jurgensen
- R.F. Kroeger
- R.W. Kilburn
- E. Swanson/N. DuBry NRC RO:III
- R.C. Callen MPSC
- G. Charnoff, Esq.
- J.M. Hennigan
- W. Lavalie EPRI
- PNSRC
- J.F. Stietzel
- E.L. Townley
- Dir., MIPC (4 copies)
- Dir., IE (40 copies)

M007
s
1/0

18101050356
P

