

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8104170569 DOC. DATE: 81/04/09 NOTARIZED: NO DOCKET #  
 FACIL: 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH. NAME: AUTHORITY AFFILIATION  
 RISCHELMING, J. L. Indiana & Michigan Electric Co.  
 RECIPIENT NAME: RECIPIENT AFFILIATION  
 Region 3, Chicago, Office of the Director

SUBJECT: Updated LER 80-009/3X-1 on 800208, steam generator 3 level indication became erratic & declared inoperable. Caused by Barton model 764 transmitter due to design problem in Foxboro model 610A power supplies. Transmitter replaced.

DISTRIBUTION CODE: A008S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2  
 TITLE: Annual, Semi-Annual & Monthly Operating Reports (OL Stage)

NOTES: Send 3 copies of all material to I&E. 05000316


ACTION:	RECIPIENT ID CODE/NAME	COPIES	COPIES		RECIPIENT ID CODE/NAME	COPIES	
			LTR	ENCL		LTR	ENCL
	VARGA, S.	04	7	7			
INTERNAL:	D/DIR, HUM	FAC07	1	1	I&E	06	2
	MPA	13	2	2	NRC PDR	02	1
	OP EX EVAL	BR09	1	1	OR ASSESS BR	10	1
	RAD ASMT BR		1	1	<u>REG. FILE</u>	01	1
	T/A DSI		1	1			
EXTERNAL:	ACRS	11	1	1	BROOKHAVEN	12	1
	LPDR	03	1	1	NSIC	05	1

APR 20 1989

TOTAL NUMBER OF COPIES REQUIRED: LTR <sup>25</sup>~~22~~ ENCL <sup>25</sup>~~22~~

JF





**INDIANA & MICHIGAN ELECTRIC COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106  
(616) 465-5901

April 9, 1981

Mr. J.G. Keppler, Regional Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-74  
Docket No. 50-316

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,  
the following report/s are submitted:

RO 80-009/03X-1.

Sincerely,

D.V. Shaller  
Plant Manager

/bab

cc: J.E. Dolan  
R.S. Hunter  
R.W. Jurgensen  
R.F. Kroeger  
R.W. Kilburn  
E. Swanson/N. DuBry RO:III  
R.C. Callen MPSC  
G. Charnoff, Esq.  
J.M. Hennigan  
W. Lavallee EPRI  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

APR 16 1981




7.2

7.2

7.2





ATTACHMENT TO LER # 80-009/03X-1

SUPPLEMENT TO CAUSE DESCRIPTION

OPERATION WAS TRACED TO THE FOXBORO MODEL 610A POWER SUPPLIES,  
RFC-12-2512 HAS BEEN INITIATED TO INSTALL MODIFICATION KITS TO CORRECT  
THIS DESIGN PROBLEM.

15