

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8804120355    DOC. DATE: 88/04/05    NOTARIZED: NO    DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH. NAME                      AUTHOR AFFILIATION  
 DAVIS, A.B.                      Region 3, Ofc of the Director  
 RECIP. NAME                      RECIPIENT AFFILIATION  
 ALEXICH, M.P.                      Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Confirmatory Action Ltr CAL-RIII-88-007 re A Blind 880405                      R  
 telcon concerning potential tampering event.    I

DISTRIBUTION CODE: IE36D    COPIES RECEIVED: LTR 1 ENCL 0    SIZE: 2                      I  
 TITLE: Immediate/Confirmatory Action Ltr (50 Dkt-Other Than Emergency Prepar    D

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES		
	ID	CODE/NAME	LTR	ENCL	ID	CODE/NAME	LTR	ENCL	
	PD3-3	LA	1	0	PD3-3	PD	1	1	/
	STANG,	J	1	1					A
INTERNAL:	NRR/DOEA/EAB	11	1	1	REG FILE	02	1	1	D
	RES/DE/EIB		1	1	RGN3 FILE	01	1	1	D
	RGN2/DRSS/EPRPB		1	1					D
EXTERNAL:	LPDR		1	1	NRC PDR		1	1	S
	NSIC		1	1					S

R  
I  
D  
S  
/  
A  
D  
D  
S

TOTAL NUMBER OF COPIES REQUIRED: LTR 11 ENCL 10

APR 05 1988

Docket No. 50-315  
Docket No. 50-316

Indiana Michigan Power Company  
ATTN: Mr. Milton P. Alexich  
Vice President  
Nuclear Operations Division  
1 Riverside Plaza  
Columbus, OH 43216

Gentlemen:

This letter confirms the conversation on April 5, 1988, between Mr. A. Blind of your staff and Mr. B. Burgess of this office, related to the potential tampering event involving foreign material found in the Unit 1 turbine driven Auxiliary Feedwater pump bearing housing at the D. C. Cook Nuclear Plant. With regard to the matters discussed, we understand that you will complete the following actions:

1. Brief plant operators and plant security personnel with regard to the above event to provide a heightened state of awareness to the presence of foreign material in undesired places and/or in equipment.
2. Inspect each Auxiliary Feedwater (AFW) pump bearing for the presence of foreign material.
3. Visually inspect accessible portions of other safety related motors/pumps for the presence of foreign material.
4. Analyze the bearing oil in the Unit 1 turbine driven Auxiliary Feedwater Pump outboard bearing for evidence of contaminants.
5. Within 30 days, provide to Region III an update on the results of the above inspections and the analysis of the Unit 1 turbine driven Auxiliary Feedwater Pump outboard bearing oil to be followed by a letter on these same subjects.

Should any further instances of potential tampering be found, we understand that you will immediately notify us. In addition, any evidence found of tampering during your inspection should be preserved for NRC review.

8804120355 880405  
PDR ADDCK 05000315  
P DCD

1/0  
IE36

APR 05 1988

Indiana Michigan Power Company

2

Should your understanding differ from that stated above, please inform this office immediately.

Sincerely,

"Original signed by A. Bert Davis"

A. Bert Davis  
Regional Administrator

cc: W. G. Smith, Jr., Plant Manager  
DCD/DCB (RIDS)  
Licensing Fee Management Branch  
Resident Inspector, RIII  
Ronald Callen, Michigan  
Public Service Commission  
EIS Coordinator, USEPA  
Region 5 Office  
Michigan Department of  
Public Health

RIII  
BIB  
Burgess/cs  
4/5/88

RIII  
Paperiello  
4/5

RIII  
Guldemon  
4/5

RIII  
Davis  
4/5

RIII  
Greenman  
4/5

RIII  
Creed

RIII  
Shafer  
MALLETT

RIII  
yes  
Worsham