REGULATORY INFORMATION DISTRIBUTION STATEM (RIDS)

ACCESSION NBR:	8008260424 DOC.DATE: 80/08/18 NOTARIZED: NO	DOCKET
FACIL:50-315	Donald C. Cook Nuclear Power Plant, Unit 1, Indiana &	05000319
50-316	Donald C. Cook Nuclear Power Plant, Unit 2, Indiana &	05000316
AUTH.NAME	AUTHOR AFFILIATION	
HUNTER, R.S.	Indiana & Michigan Electric Co.	
RECIP.NAME	RECIPIENT AFFILIATION	
DENTON, H.R.	Office of Nuclear Reactor Regulation, Director	

SUBJECT: Notifies that response to Question 5.74 of requirements of IE Bulletin 79-14 has been found to be inconsistent w/FSAR design criterion for oiping.Amend to FSAR will be filed to include correct response & actual design practice.

DISTRIBUTION CODE: A001S COPIES RECEIVED:LTR \perp ENCL ϕ SIZE: _______ TITLE: General Distribution for after Issuance of Operating Lic

NOTES:I&E:3 copies all material. Send 3 copies of all material to I&E.

A.

	RECIPIENT		COPIES LITR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL	
ACTION:	VARGA, S.	04	13	113				
INTERNAL:	D/DIR,HUM	FAC08	1	Į.	DIR, HUM FAC	07	1	1
	1%E	06	2	₫ `	NRC PDR	92	1	1
	0EI D	11	t	d	OR ASSESS BR	10	1	4
(REG FILE	01	1	1				
EXTERNAL:	ACRS	09	15	16	LPDR	03	1	
	NSTC	05	1					•

AUG 28 1980

.

05000315

05000316

INDIANA & MICHIGAN ELECTRIC COMPANY

P.O. BOX 18 Bowling green station New York, N.Y. 10004

> August 18, 1980 AEP:NRC:0455

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2 Docket Nos. 50-315 and 50-316 License Nos. DPR-58 and DPR-74

Mr. Harold R. Denton, Director Office of Nuclear Reactor Regulation U.S. Nuclear Regulatory Commission Washington, D. C. 20555

Dear Mr. Denton:

During the review efforts being made to comply with the requirements of I.E. Bulletin No. 79-14, we have found an inconsistency between the main body of the FSAR and part of our response to question 5.74. The main body of the FSAR accurately reflects the practice followed by AEP in the design of piping for the Donald C. Cook Nuclear Plant when it states for the design of "engineered safety features" that:

> "...by designing the engineered safety features to be operative under a maximum horizontal ground acceleration of 20 percent of gravity and a maximum vertical acceleration of 13.33 percent of gravity." (FSAR, page 2.5-4)

That is the practice consistently followed in the design of the Plant's engineered safety features piping systems employed at least two thirds (2/3) of the appropriate horizontal response spectrum at the base slab for the vertical acceleration. This is, incidentally, the same practice followed by at least five other facilities of similar vintage to Cook.

Our response to Question 5.74 (Amendment No. 17 to the facility's FSAR, issued in September of 1971) was consistent with the above stated FSAR design criterion except that the sentence related to piping inexplicably omitted the reference to the two thirds (2/3) fraction. Thus, it stated that:

"....The analysis of piping includes the vertical loads equal to the appropriate horizontal ground response spectrum."

8008260424

Mr. Harold R. Denton, Director

AEP:NRC:0455

This, of course, did not represent the design practice followed at the Cook Plant. While our own personnel and an outside consultant noted this erroneous response in the 1971-73 period, the efforts to correct the record apparently were not followed through to completion.

-2-

In the next two months we are filing an amendment to our FSAR. This amendment will include the corrected response to question 5.74, which will reflect the actual design practice followed at the Donald C. Cook Nuclear Plant.

Very thuly yours,

R. S. Hunter Vice President

cc: R. C. Callen G. Charnoff J. E. Dolan R. W. Jurgensen D. V. Shaller - Bridgman