	REGULAT Y INFORMATION DISTRIBUTION YSTEM (RIDS)	
ACCESSION NBR:96 FACIL:50-315 Do AUTH.NAME PISARSKY,F. BLIND,A.A. RECIP.NAME	512020052 DOC.DATE: 96/11/25 NOTARIZED: NO onald C. Cook Nuclear Power Plant, Unit 1, Indiana M AUTHOR AFFILIATION American Electric Power Co., Inc. American Electric Power Co., Inc. RECIPIENT AFFILIATION	DOCKET # 05000315

CATEGORY

1

.

C

F

T

E

· (

υ

M

E

N

Т

SUBJECT: LER 96-006-00:on 961024, interim LER-one hours action statement requirements not met for inoperable Unit 1 power operated relief block valve. Caused by incorrect assumption. Preventive actions is expected to be submitted.W/961125 ltr.

DISTRIBUTION CODE: IE22T COPIE	S RECEIVED:LTR	ENCL	SIZE: 2
TITLE: 50.73/50.9 Licensee Even	t Report (LER),	Incident	Rpt, etc.

## NOTES:

×	RECIPIENT ID CODE/NAME PD3-3 PD	COPII LTTR 1	ES ENCL 1	RECIPIENT ID CODE/NAME HICKMAN,J	COP: LTTR 1	IES ENCL 1	C F
	AEOD/SPD/RAB FILE CENTER NRR/DE/EELB NRR/DRCH/HHFB NRR/DRCH/HOLB NRR/DRPM/PECB NRR/DSSA/SRXB RGN3 FILE 01	2 1 1 1 1 1	2 1 1 1 1 1	AEOD/SPD/RRAB NRR/DE/ECGB NRR/DE/EMEB NRR/DRCH/HICB NRR/DRCH/HQMB NRR/DSSA/SPLB RES/DET/EIB	2 1 1 1 1	2 1 1 1 1 1 1	יב צ 1
EXTERNAL:	L ST LOBBY WARD NOAC MURPHY,G.A NRC PDR	- 1 1	1 1 1	LITCO BRYCE,J H NOAC POORE,W. NUDOCS FULL TXT	1 1 1	1 1 1	E C C

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25 American Electric Powr Cook Nuclear Plant One Cook Place Bridgman, MI 49106 616 465 5903



November 25, 1996

United States Nuclear Regulatory Commission Document Control Desk Rockville, Maryland 20852

> Operating Licenses DPR-58 Docket No. 50-315

**Document Control Manager:** 

In accordance with the criteria established by 10 CFR 50.73 entitled <u>Licensee Event</u> <u>Report System</u>, the following report is being submitted:

96-006-00

Sincerely,

A. alan Bh

A. A. Blind Site Vice President

/mbd

\* 1

Attachment

- c: A. B. Beach, Region III
  - E. E. Fitzpatrick
  - P. A. Barrett
  - S. J. Brewer
  - J. R. Padgett

D. Hahn Records Center, INPO NRC Resident Inspector

020018

9612020052 961125 PDR ADOCK 05000315 S PDR

JE 22 l

NRC FOR (5-92)	M 366		S. NUCLEAR REGULATORY COMMISSION									PROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95					
LICENSEE EVENT REPORT (LER)									ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.								
FACILITY NAME (1) Donald C. Cook Nuclear Plant - Unit 1										KET NUMBER (2) Page 1 50-315				if 1			
TITLE (		LER - O	ne Hour	s Ac	tion Statement F	lequiren	nents	Not Met	for Inope	orable l	Jnit 1 Pow	er Operated Re	lief Block Val	lve			
EVE	T DATE				LER NUMBER (6				T DATE		F		ILITIES INV		(9)		
монтн	DAY	YEAR	YEAR		SEQUENTIAL NUMBER	REVIS		MONTH	DAY	YEAR	FACILI	TY NAME	DOCKET NUMBER				
10	24	96	96		006	00	)	11	25	96	FACILI	TY NAME		DOCKET NUMBER			
OPERA MODE		1			RT IS SUBMITTE	D PURS	UANT	TO THE 20.2203			OF 10 C	R II: (Check			1) 5.71(	<b>b)</b>	
POL	ri i i i i i i i i i i i i i i i i i i				3(a)(1)		1	20.2203				50,73(a)(2)(jv) 73,71署					
LEVEL		89			3(a)(2)(1)			20.2203		<u></u>		50.73(a)(2)	OTHER				
			20.	220	3(a)(2)(ii)			50.36(0	o(1)			50.73(a)(2)(vii) (Specify in					
					3(a)(2)(iii)			50.36(c)(2)				50.73(a)(2)(	Abstract below				
			20.	220	3(a)(2)(iv)		X	50.73(a)(2)(1)				50.73(a)(2)(	and in Text,				
			20.	220	3(a)(2)(v)			50.73(a	)(2)(i	i)		50.73(a)(2)(x) NRC Form 366A)				366A)	
						LICEN	SEE (	CONTACT	FOR THI	S LER	(12)						
NAME											-	TELEPHONE NU	MBER (Incl	ude Ai	rea C	ode)	
Fran	k Pisars	ky, Pro	ductio	n E	ngineering - N	lechai	nical	Compo	nents	Super	visor	616	616/465-5901,x2607				
			CO	MPL	ETE ONE LINE F	OR_EAC		PONENT	EAILURE	DESCR	IBED IN	THIS REPORT (	13)		·		
CAUSE	USE SYSTEM COMPONENT MANUFACTURER REPOR		Procession of Laiss		USE •	SYSTEM	COMPONENT	MANUFACT	NUFACTURER		PORTABLE D NPRDS						
	.、	T															
		_'		NT/	L REPORT EXPE	CTED (1	4)			ti				DAY YEAR			
X YES		· · · · · · · · · · · · · · · · · · ·	فلتتعلط بتيتعن		- DELYNL-EALES			И	<u>,                                     </u>		SUBMISSION 12 20			96			
$[]^{"}$								DATE (15) 12 20 90									

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On October 24, 1996, at 1215 hours with Unit 1 in Mode 1 at 89 percent Rated Thermal Power, 1-NMO-152, the block valve for Power Operated Relief Valve (PORV) 1-NRV-152, was declared inoperable. It was subsequently determined that the valve had been inoperable since October 14, 1996, when the calculation run for 1-NMO-152 using a revised valve factor showed that the thrust required to close the valve under a design basis differential pressure was above the current thrust setting in the closed direction. As the valve was not declared inoperable until October 24, 1996, the 1 hour Action Statement requirements were not met. This interim LER is being submitted in accordance with 10CFR50.73(a)(2)(i)(B), to report a condition prohibited by the plant's Technical Specifications. The valve factor (0.4) used in the original calculation for 1-NMO-152, derived from EPRI test loop data of a similar valve, had been previously evaluated and accepted by the NRC. As part of the final evaluation the EPRI Performance Prediction computer model was to be run to determine a bounding valve factor. This run indicated a more conservative value of 0.51 should be used. However, this valve factor of 0.51 was not applied at the time the information was received, due to an incorrect assumption that the 0.4 valve factor was still applicable until an upcoming design change was implemented. When the use of the 0.4 was questioned during the Motor Operated Valve Close-out Inspection, the incorrect assumption was noted. The 0.51 valve factor was subsequently applied to the thrust calculation and the valve was declared inoperable.

The investigation into the root cause of this event continues, as does the evaluation to determine its safety significance. A final report, with a finalized root cause, safety significance and preventive actions, is expected to be submitted by December 20, 1996.