

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-251 TURKEY PT 4  
 RECIPIENT: .O'REILLY, J.P.  
 ORIGINATOR: SCHMIDT, A.D.  
 COMPANY NAME: FLA PWR & LIGHT CO  
 SUBJECT:

DOC DATE: 781127  
 ACCESSION NBR: 7812050176  
 COPIES RECEIVED:  
 LTR 1 ENCL 1  
 SIZE: 1+1

LER#78-010/03L-1 on 780911: Spent fuel pit cooling pumps mech seal failed causing 150 gallons of radioactively contaminated water to leak to paved area outside pump room caused by inadequately lubricated pump bearing.

NOTARIZED \_\_\_\_\_

DISTRIBUTION CODE: A002  
 DISTRIBUTION TITLE:  
 INCIDENT REPORTS

NAME.	ENCL?
BR CHIEF	W/4 ENCL
<u>REG FILE</u>	W/ENCL
NRC PDR	W/ENCL
I & E	W/2 ENCL
MIPC	W/3 ENCL
I & C SYSTEMS BR	W/ENCL
NOVAK/CHECK	W/ENCL
EEB	W/ENCL
AD FOR ENG	W/ENCL
PLANT SYSTEMS BR	W/ENCL
HANAUER	W/ENCL
AD FOR PLANT SYSTEMS	W/ENCL
AD FOR SYS & PROJ	W/ENCL
REACTOR SAFETY BR	W/ENCL
ENGINEERING BR	W/ENCL
KREGER/J. COLLINS	W/ENCL
POWER SYS BR	W/ENCL
E. Jordan	W/ENCL
LPDR	W/ENCL
NSIC	W/ENCL
ACRS	W/16 ENCL

FOR ACTION

ORB#1 BC

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

TOTAL NUMBER OF COPIES REQUIRED:

LTR  
 ENCL

42  
 42

NOTES:

DEC 6 1978

A01I-4

DEC 8 1958



November 27, 1978

PRN-LI-78-346

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-78-10  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: SEPTEMBER 11, 1978

SPENT FUEL PIT COOLING PUMP  
UPDATE REPORT NO. 1

The attached Licensee Event Report is being submitted to update our initial report of October 11, 1978.

Very truly yours,

*for* *JR Bensen*  
A. D. Schmidt  
Vice President  
Power Resources

MAS/cpc

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Director, Office of Management Information and Program Control (3)  
Robert Lowenstein, Esquire  
File 933.1TP

REGULATORY DOCKET FILE COPY

7812050176

11  
A002

REGULATORY DOCKET FILE COPY