OX 529100, MIAMH

		2	Milling
- INELSE	n ogræget		RED
Sector and	a sinuser	SE.	
	1	1	520 A 40
FLORIDA	POWER & F	IGHT CC	VIADANIV

September 24, 1979 L-79-269

Mr. James P. O'Reilly, Director, Region II Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

USNRC REGION I

79 SEP 26 All: 05 .

Dear Mr. O'Reilly:

Re: RII:JPO 50-250, 50-251 <u>IE Bulletin 79-18</u>

We have reviewed the subject Bulletin and a response for Turkey Point Units 3 and 4 is attached.

Very truly yours,

hur Robert E. Uhrig

Vice President Advanced Systems & Technology

REU/MAS/cph

Attachment

cc: Office of Inspection and Enforcement, Division of Reactor Operations Inspection Robert Lowenstein, Esquire

PO2 2910090

PEOPLE ... SERVING PEOPLE

OFFICIAL COPY.



•

.

٨

•

• *é* 

## ATTACHMENT

Re: RII:JPO 50-250, 50-251 IE Bulletin 79-18

We have reviewed the in situ configuration and performance of the Turkey Point site communications network. The evaluation consisted of a review of:

- Preoperational Procedure T9800.1, "Functional Test of Communication Systems"
- 2. Noise Surveys of Turkey Point Unit Nos. 3 & 4 performed to determine areas requiring hearing protection
- 3. Critiques of Emergency Drills
- 4. The Emergency Plan and implementing procedures
  - EP 20109 Local Evacuation and Personnel Accountability
  - EP 20110 Owner Controlled Area Evacuation
  - EP 20112 Communications Network
  - EP 20113 Emergency Procedure Drills and Alarm Tests

Our review has identified plant areas where the audibility of the Public Address (PA) portion of the communication system may be improved. As such, a Plant Change/Modification has been prepared and is being implemented. Completion is scheduled for November 1979.

We feel that the above modification will ensure that alarm systems and evacuation announcements are clearly audible throughout all plant areas. Additional assurance is provided via existing administrative and procedural controls.