

APPENDIX B

NOTICE OF DEVIATION

Florida Power and Light Company
Turkey Point

License Nos. DPR-31 and DPR-41

Based on the results of the NRC inspection conducted on February 1-29, 1980, certain of your activities appear to deviate from your commitments to the Commission.

As indicated in paragraph 5 of IE Inspection Report 50-250-251/79-24, a commitment was made to have available by October 1979, for use in final, approved form, procedures covering the following:

- ° Auxiliary Feedwater Pump Turbine Overhaul
- ° Auxiliary Feedwater Pump Turbine Throttle Trip Valve Overhaul
- ° Auxiliary Feedwater Pump Overhaul and Maintenance

Contrary to the above, such procedures had not been made available for use in final approved form as of February 28, 1980.

