

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | T | P | S | 3 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 1 | 4 | 9

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 1 | 2 | 1 | 5 | 1 | 0 | 7 | 0 | 1 | 6 | 2 | 1 | 0 | 8 | 1 | 0 | 3 | 0 | 1 | 7 | 2 | 1 | 1 | 8 | 1 | 0 | 9

02 | The daily calibration of the Unit 3 nuclear power range channel which
03 | consists of a thermal power calculation was not performed on June 20, 1980
04 | as required by Technical Specification 4.1 (Table 4.1-1, Item 1). The
05 | maximum allowable time interval of 24 hours was exceeded by approximately
06 | 9 hours. Performance of the calibration on 6/21/80 showed no abnormalities.
07 |
08 |

09 | I | E | 11 | A | 12 | A | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16 | 17 | 8 | 18 | 0 | 19 | 0 | 20 | 1 | 21 | 2 | 22 | 0 | 23 | 3 | 24 | L | 25 | 26 | X | 27 | H | 28 | Z | 29 | Z | 30 | 0 | 31 | 0 | 32 | 0 | 33 | 0 | 34 | 0 | 35 | N | 36 | N | 37 | Z | 38 | Z | 39 | 9 | 40 | 9 | 41 | 9 | 42 | 9 | 43 | 9 | 44 | 9 | 45 | 9 | 46 | 9 | 47 | 26

10 | The missed surveillance resulted from personnel error due to a misunder-
11 | standing between the person performing the test and the person responsible
12 | for ensuring the surveillance was performed. The personnel involved have
13 | been counselled concerning proper verification of surveillance testing.
14 |

15 | E | 23 | 1 | 24 | 0 | 25 | 0 | 26 | 0 | 27 | 0 | 28 | NA | 29 | A | 30 | Operator observation | 31 | 32 | 33 | 34 | NA | 35 | NA | 36 | 37 | 0 | 38 | 0 | 39 | 0 | 40 | Z | 41 | NA | 42 | 0 | 43 | 0 | 44 | 0 | 45 | NA | 46 | Z | 47 | NA | 48 | N | 49 | NA | 50 |

NAME OF PREPARER: P. L. Pace PHONE: 305/552-3801

8008050397

