

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | F | L | T | P | S | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 9

CONT

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 1 | 2 | 5 | 1 | 0 | 7 | 0 | 1 | 6 | 2 | 0 | 8 | 1 | 0 | 3 | 0 | 1 | 7 | 2 | 1 | 1 | 8 | 1 | 0 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | The daily calibration of the Unit 3 nuclear power range channel which  
03 | consists of a thermal power calculation was not performed on June 20, 1980  
04 | as required by Technical Specification 4.1 (Table 4.1-1, Item 1). The  
05 | maximum allowable time interval of 24 hours was exceeded by approximately  
06 | 9 hours. Performance of the calibration on 6/21/80 showed no abnormalities.  
07 |  
08 |

09 | I | E | 11 | A | 12 | A | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16  
17 | 8 | 0 | 0 | 1 | 2 | 0 | 3 | L | 1  
18 | X | 19 | H | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | N | 24 | Z | 25 | Z | 9 | 9 | 9 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The missed surveillance resulted from personnel error due to a misunder-  
11 | standing between the person performing the test and the person responsible  
12 | for ensuring the surveillance was performed. The personnel involved have  
13 | been counselled concerning proper verification of surveillance testing.  
14 |

15 | E | 23 | 1 | 0 | 0 | 0 | 29 | NA | A | 31 | Operator observation 32  
16 | Z | 33 | Z | 34 | NA | NA | NA | 36  
17 | 0 | 0 | 0 | 37 | Z | 38 | NA  
18 | 0 | 0 | 0 | 40 | NA  
19 | Z | 42 | NA  
20 | N | 44 | NA

NAME OF PREPARER P. L. Pace

PHONE: 305/552-3801

