

USNRC REGION II  
ATLANTA, GEORGIA



30 JUL 31 AM : 39

July 28, 1980  
L-80-240

*Central File*  
*50-250*  
*251*

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO  
50-250, 50-251  
IE Bulletin 80-16

Florida Power and Light Company has examined the Turkey Point facilities as requested by the subject Bulletin, and has determined that no Rosemount 1151 or 1152 pressure transmitters with either "A" or "D" codes are installed in any safety related applications and that there are no plans to install any of these transmitters in safety related applications.

Very truly yours,

*Robert E. Uhrig*  
Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/PLP/pah

cc: J. P. O'Reilly, Region II  
Harold F. Reis, Esquire

8008140473 *P*

OFFICIAL COPY

PEOPLE...SERVING PEOPLE

