

### LICENSEE EVENT REPORT

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[01] [7] [8] [9] | F I L I T I P I S I 3 | [2] [14] [15] | 0 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 | [3] [25] [26] | 4 1 1 1 1 1 1 1 | [4] [37] [38] [39] [40] | [5] [41] [42]

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T  
[01] [7] [8] | REPORT SOURCE | L [6] [10] [11] [12] [13] [14] [15] [16] [17] | [18] [19] [20] [21] [22] [23] [24] [25] | [26] [27] [28] [29] [30] [31] [32] [33] | [34] [35] [36] [37] [38] [39] [40] [41] | [42] [43] [44] [45] [46] [47] [48] [49] | [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[02] | During power operation, a DC ground was experienced on the 3B battery bus. |

[03] | Investigation showed a problem with the control power to 4160 V breaker |

[04] | 3AB10, for the 3B Heater Drain Pump, which prevented the breaker from |

[05] | being remotely tripped. This is reportable pursuant to TS 6.9.2.b in that |

[06] | this breaker would not have tripped to clear the 3B 4160 V bus in response |

[07] | to a bus stripping signal. The breaker was tripped manually. |

[08] [7] [8] [9] [10] [11] [12] [13] [14] [15] [16] [17] [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
[09] [7] [8] [9] [10] [11] [12] [13] [14] [15] [16] [17] [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

[17] LEA/RO REPORT NUMBER [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

EVENT YEAR [810] SEQUENTIAL REPORT NO. [0128] OCCURRENCE CODE [03] REPORT TYPE [L] REVISION NO. [0]

ACTION TAKEN [B] FUTURE ACTION [Z] EFFECT ON PLANT [Z] SHUTDOWN METHOD [Z] HOURS [00100] ATTACHMENT SUBMITTED [N] APPROX. FORM SUB. [N] PRIME COMP. SUPPLIER [A] COMPONENT MANUFACTURER [GIBO]

[10] | Investigation showed shorted control circuit wiring between 3AB10 and |

[11] | its local start station. The failure was caused by steam entering the |

[12] | electrical box and shorting out the circuit. This resulted in burning out |

[13] | the trip coil of the breaker. The circuit and conduit have been rerouted |

[14] | and the breaker was replaced with a spare. |

[15] [7] [8] [9] [10] [11] [12] [13] [14] [15] [16] [17] [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

FACILITY STATUS [E] % POWER [1100] OTHER STATUS [NA] METHOD OF DISCOVERY [A] DISCOVERY DESCRIPTION [Operator Observation]

[16] [7] [8] [9] [10] [11] [12] [13] [14] [15] [16] [17] [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

ACTIVITY CONTENT RELEASED OF RELEASE [Z] [Z] AMOUNT OF ACTIVITY [NA] LOCATION OF RELEASE [NA]

[17] [7] [8] [9] [10] [11] [12] [13] [14] [15] [16] [17] [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

PERSONNEL EXPOSURES NUMBER [00] TYPE [Z] DESCRIPTION [NA]

[18] [7] [8] [9] [10] [11] [12] [13] [14] [15] [16] [17] [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

PERSONNEL INJURIES NUMBER [00] DESCRIPTION [NA]

[19] [7] [8] [9] [10] [11] [12] [13] [14] [15] [16] [17] [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

LOSS OF OR DAMAGE TO FACILITY TYPE [Z] DESCRIPTION [NA]

[20] [7] [8] [9] [10] [11] [12] [13] [14] [15] [16] [17] [18] [19] [20] [21] [22] [23] [24] [25] [26] [27] [28] [29] [30] [31] [32] [33] [34] [35] [36] [37] [38] [39] [40] [41] [42] [43] [44] [45] [46] [47] [48] [49] [50] [51] [52] [53] [54] [55] [56] [57] [58] [59] [60]

PUBLICITY ISSUED DESCRIPTION [NA] NRC USE ONLY

NAME OF PREPARER: P. L. Pace PHONE: (305) 552-3801

