

APPENDIX A

NOTICE OF VIOLATION

Florida Power and Light Company  
Turkey Point 4

Docket No. 50-251  
License No. DPR-41

As a result of the inspection conducted on January 1-21, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violations were identified:

Technical Specification 6.8 requires written procedures for safety related equipment maintenance. Licensee administrative procedure 0190.19, Control of Maintenance on Nuclear Safety Related Systems, require plant work orders (PWO's) to be sufficiently detailed to accomplish work safety.

Contrary to the above, on January 3 and 6, 1981 PWO's 7922 and 8972 were not sufficiently detailed for work on safety related systems in that: The subject PWO's failed to identify concurrent maintenance and actual operating conditions. PWO 7922 did not identify the specific use of inputting test signals and PWO 8972 failed to reference the appropriate off-normal operating procedure for restoring the Safeguard racks to their normal operating condition. Work conducted under both of these PWO's caused inadvertent Engineered Safety Feature actuations.

This is a Severity Level V Violation (Supplement I.E.).

Pursuant to the provisions of 10 CFR 2.201, Florida Power and Light Company is hereby required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Date: MAR 17 1981

8106080440

