

APPENDIX B

NOTICE OF DEVIATION

Florida Power and Light Company  
Turkey Point 4

Docket No. 50-251  
License No. DPR-41

Based on the results of the U.S. Nuclear Regulatory Commission inspection conducted on January 1-28, 1981 certain of your activities appear to deviate from your commitments to the Commission as indicated below:

Your September 16, 1980 response to IE Bulletin No. 80-20, Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches, stated in response 2 that a continuity test will be repeated on all the control switches listed at least every ninety-two (92) days after the initial test.

Contrary to the above, the continuity test was not repeated on the required switches until , more than 92 days had elapsed since the initial test. The tests were performed on November 29, 1980 after the resident inspector's identification.

This is a deviation..

8106080443

