


USNRC REGION II
ATLANTA, GEORGIA



82 JAN 4 A 8:42

December 29, 1981
L-81-541

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 & 4
Docket Nos. 50-250, 50-251
IE Inspection Report 81-25

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

A handwritten signature in cursive script that reads 'Robert E. Uhrig'.

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/PLP/cab

cc: Harold F. Reis, Esquire

8202050109 820120
PDR ADOCK 05000250
Q PDR

71

1971
1972
1973
1974
1975
1976
1977
1978
1979
1980
1981
1982
1983
1984
1985
1986
1987
1988
1989
1990
1991
1992
1993
1994
1995
1996
1997
1998
1999
2000
2001
2002
2003
2004
2005
2006
2007
2008
2009
2010
2011
2012
2013
2014
2015
2016
2017
2018
2019
2020
2021
2022
2023
2024
2025
2026
2027
2028
2029
2030
2031
2032
2033
2034
2035
2036
2037
2038
2039
2040
2041
2042
2043
2044
2045
2046
2047
2048
2049
2050
2051
2052
2053
2054
2055
2056
2057
2058
2059
2060
2061
2062
2063
2064
2065
2066
2067
2068
2069
2070
2071
2072
2073
2074
2075
2076
2077
2078
2079
2080
2081
2082
2083
2084
2085
2086
2087
2088
2089
2090
2091
2092
2093
2094
2095
2096
2097
2098
2099
2100

1971

RE: TURKEY POINT UNITS 3 & 4
DOCKET NO. 50-250, 50-251
IE INSPECTION REPORT 81-25

FINDING:

Technical Specification 6.8.1 requires that written procedures be implemented for maintenance of safety related equipment. Maintenance Procedure 7307.4, Auxiliary Feedwater Pump Turbine Throttle Trip Valve Overhaul, is provided for maintenance and specifies retention as a Quality Assurance record.

Contrary to the above, procedure MP 7307.4 was not implemented or retained as required during the performance of plant work order PWO-2838 on September 30, 1981, for maintenance related to the "A" Auxiliary Feedwater Pump.

RESPONSE.

1. FPL concurs with the finding.
2. This finding occurred because the preparer of the work order did not know a procedure existed to do the maintenance. Prior to the job, the procedure index was reviewed seeking a procedure that addressed the Emergency Trip Valve for the auxiliary feed pumps (this is the name given in the Technical Manual for this unit). There was no procedure listed with a title that specifically addressed this item by that name. The procedure that actually addresses this valve is titled "Auxiliary Feedwater Pump Turbine Throttle Trip Valve Overhaul". During this review of the Index the person did not realize that this valve was included in this maintenance procedure. (A more thorough review concluded this valve was included). The work was accomplished under a Quality Control approved Plant work order which gave sufficient written instructions for the maintenance work to be performed. The mechanic assigned to perform this task was instructed to document a detailed description of this task for the future development of a procedure to cover this task.
3. After the task was completed on the "A" auxiliary feed pump it was discovered that Maintenance Procedure 7307.4 did in fact cover this work. The mechanic's detailed description was reviewed and contained all the steps in the approved procedure. After this review it was concluded that the unit could be returned to service and the test conducted proved satisfactory.
4. Mechanical Maintenance Department Supervisors, Generation Equipment Maintenance System Planners, and Coordinators have been reminded to review the procedure index and to ensure that they are familiar with the content of the procedures to preclude a recurrence.
5. Full compliance was achieved by December 23, 1981.




STATE OF FLORIDA)
)
COUNTY OF DADE) ss.

Robert E. Uhrig, being first duly sworn, deposes and says:


That he is Vice President of Florida Power & Light Company, the herein;

That he has executed the foregoing document; that the statements made in this said document are true and correct to the best of his knowledge, information, and belief, and that he is authorized to execute the document on behalf of said


Robert E. Uhrig

Subscribed and sworn to before me this

29 day of December, 1981


Cheryl Z. Fredrick
NOTARY PUBLIC, in and for the County of Dade,
State of Florida

My commission expires: Notary Public, State of Florida at Large
My Commission Expires October 30, 1983
Bonded thru Maynard Bonding Agency

LABORATORY
JAN 19 1964
FBI - WASHINGTON