



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION II
 101 MARIETTA STREET, N.W.
 ATLANTA, GEORGIA 30323

OCT 04 1985

Report Nos.: 50-250/85-29, 50-251/85-29, 50-335/85-22 and 50-389/85-22

Licensee: Florida Power and Light Company
 9250 West Flagler Street
 Miami, FL 33101

Docket Nos.: 50-250, 50-251, 50-335
 and 50-389

License Nos.: DPR-31, DPR-41,
 DPR-67 and NPF-16

Facility Name: Turkey Point and St. Lucie

Inspection Conducted: August 19-21, 1985

Inspector: W. W. Stansberry
 W. Stansberry

9/24/85
 Date Signed

Approved by: A. L. Cunningham
 A. L. Cunningham, Acting Section Chief
 Emergency Preparedness
 Division of Radiation Safety and Safeguards

09/26/85
 Date Signed

SUMMARY

Scope: This special announced inspection entailed 18 inspector-hours on site and at the General Office in the areas of Emergency Preparedness, Emergency Response Facilities, NRC Response Team Coordination, and NRC Hurricane Response Equipment, Coordination and Procedures.

Results: Of the four areas inspected, no violations or deviations were identified.

8510220396 851004
 PDR ADDCK 05000250
 Q PDR

10



REPORT DETAILS

1. Persons Contacted

Licensee Employees

- A. Meade, Security Office (TWC)
- M. Hardage, T&D Supervisor, Midway Center
- *J. Maisler, Acting Emergency Planning Supervisor
- *D. Mothena, Emergency Planning Coordinator
- G. Casto, Emergency Planning Coordinator

*Attended exit interview

2. Exit Interview

The inspection scope and findings were summarized on August 21, 1985, with those persons indicated in paragraph 1 above.

The licensee did not identify as proprietary any of the materials provided to or reviewed by the inspector during this inspection.

3. Licensee Action on Previous Enforcement Matters

This subject was not addressed in the inspection.

4. Independent Inspection Effort (92706)

The inspector held discussions with licensee representatives regarding emergency preparedness, emergency response facilities, Region II Incident Response Teams, NRC-Licensee interface during emergencies and NRC Hurricane equipment, procedures and coordination. Experience and lessons - learned from the Full Field Exercise of the Federal Radiological Emergency Response Plan at Plant St. Lucie, in March 1984 were discussed. A draft copy of the logistical needs of the Region II Incident Response Teams was presented and discussed. The inspector discussed NRC response team organization, NRC concept of operation, roles and responsibility of the site team, and interface areas between the NRC and licensee response team. The NRC Hurricane response team and High Frequency Radio equipment installed at their facilities were reviewed and discussed. The licensee was informed that the antenna and tuners have been mounted and should not be dismounted. Region II future plans to improve the hurricane communication system was also discussed.