

SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30323

DEC 16 1987



Report Nos.: 50-250/87-47 and 50-251/87-47

Licensee: Florida Power and Light Company
9250 West Flagler Street
Miami, FL 33102

Docket Nos.: 50-250 and 50-251

License Nos.: DRP-31 and DPR-41

Facility Name: Turkey Point 3 and 4

Inspection Conducted: November 16-20, November 23-24, 1987

Inspectors: Orysia M. Masnyk 12-15-87
Orysia M. Masnyk, Physical Security Specialist Date Signed

David R. McGuire 12-15-87
David R. McGuire, Chief, Physical Security Section Date Signed

Approved by: D. R. McGuire 12-15-87
D. R. McGuire, Chief, Physical Security Section Date Signed
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

SUMMARY

Scope: This routine, unannounced inspection and special announced management meeting involved a review of the following areas: Security Program Audit; Barriers - Protected and Vital Areas; Compensatory Measures; Access Control of Personnel, Packages, and Vehicles; Detection Aids - Protected and Vital Areas; Alarm Stations; and Communications. Additionally, the inspector evaluated the circumstances surrounding an officer leaving a vital area compensatory post. A management meeting was held on November 29, 1987.

Results: Four violations of regulatory requirements were confirmed: Inadequate Compensatory Measures, Failure to Properly Control Access to the Protected Area, Inadequate Lighting, and Inadequate Search Prior to Revitalization.

8712220281 871216
PDR ADDCK 05000250
Q PDR

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION