

Official

MEMORANDUM FOR: Thomas E. Murley, Director
Office of Nuclear Reactor Regulation

FROM: J. Nelson Grace, Regional Administrator

SUBJECT: MONTHLY STATUS REPORT ON TURKEY POINT

The purpose of this memorandum is to advise senior NRC management of the status of the Turkey Point Project.

The enclosure discusses recent operating events and performance trends.

original signed by
J. Nelson Grace

Enclosure:
Turkey Point Status Report
(June 16 - July 31, 1988)

cc w/encl:
W. Taylor, DEDRO
S. Varga, NRR

W. F. Conway
Senior Vice President
P. O. Box 14000
Nuclear Energy Department
Juno Beach, FL 33408-0420

W. Odom, Vice President
Turkey Point Nuclear Plant
P.O. Box 029100
Miami, FL 33102

W. E. Cross, Plant Manager
Turkey Point Nuclear Plant
P. O. Box 029100
Miami, Florida 33102

W. Harold F. Reis, Esq.
Newman and Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

W. John T. Butler, Esq.
Steel, Hector and Davis
4000 Southeast Financial Center
Miami, Florida 33131-2398

cc w/encl: (Continued on page 2)

8809010144 880731
PDR ADOCK 05000250
R PNU

11
EE01

AUG 2 1988

cc w/encl: (Continued)
U.S. Environmental Protection Agency
Region IV
Regional Radiation Representative
345 Courtland Street, N.W.
Atlanta, Georgia 30308

Attorney General
Department of Legal Affairs
The Capitol Building
Tallahassee, Florida 32301

Alan Schubert, Public Health
Physicist Manager
Office of Radiation Control
Radiological Health Services
Department of Health and Rehabilitative
Services
1317 Winewood Boulevard
Tallahassee, Florida 32301

Administrator
Department of Environmental Regulation
Power Plant Siting Section
State of Florida
Twin Towers
2600 Blair Stone Road
Tallahassee, Florida 32301

State Planning and Development
Clearinghouse
Office of Planning and Budgeting
Executive Office of the Governor
The Capitol Building
Tallahassee, Florida 32301

Intergovernmental Coordination and Review
Office of Planning and Budgeting
Executive Office of the Governor
The Capitol Building
Tallahassee, Florida 32301

Martin H. Hodder, Esq.
1131 N.E. 86th Street
Miami, Florida 33130

bcc w/encl:
DRC Resident Inspector
Document Control Desk
State of Florida

RII
MSL
CChristensen
8/11/88

RII
R
RCrljenjak
8/11/88

RII
BN
BNWilson
8/11/88

RII
Ch
Cherl
8/11/88

RII
LR
LReyes
8/11/88

RII
ME
MEinst
8/11/88

as revised



o

3

x

AUG 22 1988

ENCLOSURE

TURKEY POINT STATUS REPORT
(JUNE 16 - JULY 31, 1988)

1. Plant Status

Unit 3 was in mode 1
Unit 4 was in mode 1

2. Facility Operations Summary

Unit 3 was operating at 100 percent power and has been on line since March 30, 1988; 124 days.

Unit 4 was operating at 100 percent power and has been on line since May 28, 1988; 64 days.

The Turkey Point dual unit operating record was surpassed on July 17, 1988, and Unit 3 surpassed its continuous operating record on July 29, 1988.

3. Items of Interest

On July 6, 1988, the licensee reported a Physical Security Event. A Health Physics technician tested positive for drugs. This person had tested positive for drugs on January 8, 1988, and entered the Employee Assistance Program. The person's access was revoked and employment was terminated.

On July 9, 1988, the licensee made a 48-hour telephone notification to the NRC concerning suspect flanges identified in response to NRC Bulletin 88-05. The licensee identified 121 flanges installed in the Unit 4 ICW/CCW heat exchanger Amertap system. A similar telephone notification was made July 15, 1988, concerning 24 suspect flanges found in the steam generator wet layup system. The licensee is currently evaluating data obtained from testing the subject flanges.

On July 16, 1988, at 1240, with both units at 100 percent power, an actuation of the process radiation monitor system (PRMS) containment and control room ventilation isolation occurred. The isolation was caused by an apparent increase in Unit 4 containment airborne activity levels, which was verified by a sample taken from the containment. The licensee conducted a visual inspection of the accessible areas of the containment and observed no signs of reactor coolant system (RCS) leakage. Inspection of the PRMS R-11 detector found the detector jammed against the paper. The detector was

TEO
1/1

AUG 22 1988

replaced and reset to the proper height (1/16") above the paper. The licensee concluded that the most probable cause for the increased activity level was due to an increase in seal leakage for reactor coolant pump (RCP) 4B. The licensee continues to monitor RCS leak rate and containment activity levels.

On July 16, 1988, at 1645, with both units at 100 percent power, the rod position indicator (RPI) for Unit 3 control rod G-5 was found to indicate greater than 12 steps difference than the other Bank "A" RPI indications. This required a forced load reduction and the performance of a flux map to verify the actual position of the control rod. The flux trace indicated the actual position of the rod was at 228 steps, the RPI was aligned, and the unit was returned to 100 percent power. See paragraph 4 for further discussion of this issue.

The following Licensee Event Reports were received during this period:

- 50-250/88-09 - Quality Assurance Discovered Missed Technical Specification Surveillance for Station Battery Pilot Cell Rotation and EDG Fuel Oil Sampling Analysis. Event date - May 27, 1988.
- 50-250/88-10 - Containment Ventilation and Control Room Ventilation Isolation While Containment Particulate Radiation Monitor Setpoint Was Being Checked on Two Separate Occasions. Event date - May 28, 1988.
- 50-250/88-11 - Mispositioned Diesel Oil Transfer Valve Due to Personnel Error Results in Potential Loss of Long Term Fuel Supply to Emergency Diesel Generators. Event date - May 31, 1988.
- 50-250/88-12 - Verification of Fire Detection Operability Not Performed as Required by Technical Specification 3.14 Due to Weaknesses in Administrative Controls of Penetration Seal Surveillance Test. Event date - June 12, 1988.

In letter dated June 23, 1988, the licensee supplied to the NRC their Emergency Power System Enhancement Report. This report discusses the installation of two additional emergency diesel generators plus the enhancements to the emergency power distribution system at Turkey Point. The project is scheduled for completion in 1990 during a dual unit outage.

An Enforcement Conference was held on July 13, 1988. The purpose of the meeting was to discuss the isolation of the emergency diesel generator fuel oil system. The results of the conference will be provided in separate correspondence.

4. NRC Staff Activities During the Period

During the week of July 18, 1988, a Facilities Radiation Protection Section, DRSS, inspection was conducted in the areas of radiation control, internal and external exposure, shipment of radwaste, solid waste, and training and qualification.

The resident inspectors' monthly report covered the period of June 25 through July 25, 1988. One finding was identified:

A Reactor Control Operator (RCO) trainee performing peak shift control rod position verification, noticed Control Bank "A", rod G-5, indicating greater than 12 steps misaligned with other rods in the bank. The OFF Normal Operating Procedure (ONOP) requires, within 8 hours, either a flux map be performed to determine the position of the rod or reduce power to less than 50 percent. A review of the log readings for the day shift revealed that this condition had existed approximately 9 hours, but the RCO failed to recognize the problem. Since the 8 hours had already elapsed, a unit load reduction was commenced while an incore flux map was performed. The rod was verified to be aligned with the other rods in the bank and the load reduction was stopped at 97 percent.

During the week of June 21, 1988, an Operational Programs Section, DRS, inspection was conducted in the area of previous inspection findings. The result of this inspection was included in the resident inspector monthly report.

During the week of June 27, 1988, a Physical Security Section, DRSS, inspection was conducted in the area of routine security modules.

During the week of July 5, 1988, a Test Program Section, DRS, inspection was conducted in the area of testing of Pipe Support and Restraint Systems and Containment Tendon surveillance.

An Enforcement Conference was held on April 21, 1988, on Emergency Preparedness issues. The results of the conference are as follows: Two Severity Level IV violations in the areas of inaccurate dose estimates, and failure to establish and implement computer software control procedures.

On June 24, 1988, AEOD completed its assessment of the independent management appraisal. The licensee will provide a response to the independent management appraisal and the AEOD report on August 15, 1988.

The next monthly management meeting with FPL is scheduled for August 4, 1988.