

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-250
 UNIT NAME Turkey Point Unit #3
 DATE November 15, 1988
 COMPLETED BY D. M. Bonett
 TELEPHONE (407) 694-4432

****CORRECTED COPY****

REPORT MONTH October, 1988

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
10	881001	F	723.6	A	1	250-88-024	CF	PUMPXX	<p>During the monthly Residual Heat Removal Pump (RHR) inservice test, seal leakage in the 3A RHR pump resulted in the pump being declared out of service. The unit was shut down and the 3A RHR pump leaking seal was replaced with a spare shaft seal.</p> <p>The outage was further extended to repair the pressurizer heaters and replace electrical generator rotor.</p>

1
 F Forced
 S Scheduled

2
 Reason
 A - Equipment Failure (Explain)
 B - Maintenance or Test
 C - Refueling
 D - Regulatory Restriction
 E - Operator Training & License Examination
 F - Administrative
 G - Operational Error (Explain)
 H - Other (Explain)

3
 Method
 1 - Manual
 2 - Manual Scram
 3 - Automatic Scram
 4 - Continued
 5 - Load Reduction
 9 - Other (Explain)

4
 Exhibit G - Instructions for Preparation of Data Entry Sheets Licensee Event Report (LER) File (NUREG-0161)

5
 Exhibit 1 - Same Source

8812200015 881213
 PDR ADDCK 05000250
 PDC



6

Handwritten scribbles and marks in the middle-left area of the page.

Handwritten marks or characters in the lower-right area of the page.