

# SAFEGUARDS INFORMATION



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30323

OCT 23 1986

Report Nos.: 50-250/86-40 and 50-251/86-40

Licensee: Florida Power and Light Company  
9250 West Flagler Street  
Miami, FL 33102

Docket Nos.: 50-250 and 50-251

License Nos.: DPR-31 and DPR-41

Facility Name: Turkey Point 3 and 4

Inspection Conducted: September 28-29, 1986

Enforcement Conference: October 1, 1986

Inspector: Orysia M. Masnyk  
Orysia M. Masnyk, Physical Security Specialist

10-23-86  
Date Signed

Approved by: D. R. McGuire  
D. R. McGuire, Chief, Physical Security Section  
Nuclear Materials Safety and Safeguards Branch  
Division of Radiation Safety and Safeguards

10-23-86  
Date Signed

## SUMMARY

Scope: This nonroutine, special inspection involved a review of scaffolding which provided a pathway from the protected area into a vital area, discovered by the Senior Resident Inspector on September 25, 1986.

Results: A violation of regulatory requirements was identified: 86-38-04, Inadequate Compensatory Measures.

8610310200 861023  
PDR ADCK 05000250  
Q PDR

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED.

# SAFEGUARDS INFORMATION

