



# SAFEGUARDS INFORMATION

UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30323

JUN 03 1987

Report Nos. 50-250/87-25 and 50-251/87-25

Licensee: Florida Power and Light Company  
9250 West Flagler Street  
Miami, FL 33408

Docket Nos.: 50-250 and 50-251

License Nos.: DPR-31 and DPR-41

Facility Name: Turkey Point

Inspection Conducted: May 11-15, 1987

Inspector: William J. Tobin  
Orysia M. Masnyk, Physical Security Specialist

6/1/87  
Date Signed

Approved by: William J. Tobin  
D. R. McGuire, Chief, Physical Security Section  
Nuclear Materials Safety and Safeguards Branch  
Division of Radiation Safety and Safeguards

6/1/87  
Date Signed

## SUMMARY

Scope: This routine, unannounced inspection involved a review of the following areas: Security Plans and Procedures; Barriers - Protected and Vital Areas; Compensatory Measures; Detection Aids - Protected and Vital Areas; Access Control of Personnel, Packages, and Vehicles; and Contingency Plan Implementation.

Results: Two violations of regulatory requirements were identified:

- Failure to control personnel and equipment access into Containment.
- Inadequate vehicle search.

8706110032 870603  
PDR ADOCK 05000250  
Q PDR

# SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION  
UPON SEPARATION THIS  
PAGE IS UNCONTROLLED.

10-1-77

