



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION II
 101 MARIETTA ST., N.W.
 ATLANTA, GEORGIA 30323

Report Nos.: 50-250/89-05 and 50-251/89-05

Licensee: Florida Power and Light Company
 9250 West Flagler Street
 Miami, FL 33102

Docket Nos.: 50-250 and 50-251

License Nos.: DPR-31 and DPR-41

Facility Name: Turkey Point 3 and 4

Inspection Conducted: January 30 - February 3, 1989

Inspector:

[Signature]
 R. W. Newsome

2/13/89

Date Signed

Approved by:

[Signature]
 J. J. Blake, Chief
 Materials and Processes Section
 Engineering Branch
 Division of Reactor Safety

2/13/89

Date Signed

SUMMARY

Scope

This routine, announced inspection, was conducted on site in the areas of replacement and repair of the Reactor Vessel Bottom Mounted Instrumentation conduits at the Seal Tables and review of the Nondestructive Examination (NDE) records for the Ultrasonic indications revealed during the inservice inspection examinations conducted on the Unit 4, Steam Generator B, circumferential weld.

Results

In the areas inspected, violations or deviations were not identified.

The licensee was very receptive to any suggestions made by the NRC during this inspection. There appeared to be good management involvement during the repair and replacement activities of the conduits at the seal table and also during the activities for resolution of indications in the steam generator weld in Unit 4. All other areas appeared to be adequately addressed.

