

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9007240090 DOC. DATE: 90/07/20 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME AUTHOR AFFILIATION
 HARRIS, K.N. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Advises that comments on NRC SE re implementation of station blackout rule will be provided by 900921.

DISTRIBUTION CODE: A050D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: Station Blackout (USI A-44) 10CFR50.63, MPA A-22

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES		
	ID CODE/NAME		LTR	ENCL		ID CODE/NAME		LTR	ENCL	
	PD2-2 PD		1	1		EDISON, G		1	1	
INTERNAL:	NRR PD1-4PM TAM		1	1		NRR/DET/ESGB 8D		2	2	
	NRR/DST/SELB		3	3		NRR/DST/SPLB8D1		3	3	
	NRR/DST/SRXB8E		1	1		<u>REG FILE</u> 01		1	1	
EXTERNAL:	LPDR		1	1		NRC PDR		1	1	
	NSIC		1	1						

NOTE TO ALL "RIDS" RECIPIENTS:


PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 16 ENCL ~~16~~ 0

*MA 14
 sub*

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S





FPL

P.O. Box 14000, Juno Beach, FL 33408-0420

JUL 20 1990

L-90-275
10 CFR 50.63

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket No. 50-250 and 50-251
Implementation Of The Station Blackout Rule

By letter dated June 15, 1990, (G. Edison to J.H. Goldberg) the Nuclear Regulatory Commission (NRC) transmitted to Florida Power and Light (FPL) the NRC's Safety Evaluation (SE) associated with FPL's proposed design to meet the requirements of the Station Blackout Rule (10 CFR 50.63) at Turkey Point.

Pursuant to 10 CFR 50.63 (c) (4), FPL will make plant modifications as described in FPL letter L-89-144, dated April 17, 1989 and FPL letter L-90-56, dated March 29, 1990. These modifications will be performed during the 1991 dual unit outage, in parallel with the Emergency Power System enhancement. Documentation necessary to demonstrate compliance with 10 CFR 50.63 (c) (2) for both Turkey Point units will be available for inspection 90 days after return to power from the 1991 dual unit outage.

FPL will provide comments on the NRC's SE by September 21, 1990. Should there be any questions, please contact us.

Very truly yours,

K. N. Harris
Vice President
Turkey Point Plant Nuclear

KNH/GS

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9007240090 900720
PDR ADDCK 05000250
P PDC

A050
110

111

101 11 101

10 101 101

10 101