

REVISED COPY
SUMMARY OF OPERATING EXPERIENCE

DOCKET NO. 50-250

UNIT Turkey Point #3

DATE August 10, 1990

COMPLETED BY R. A. Tierney

TELEPHONE (305) 246-6970

REPORT MONTH June, 1990

Unit 3 was returned to service on June 3, 1990 from a scheduled refueling and maintenance outage that began on February 3, 1990. On June 4 Unit 3 was removed from service to repair the Feedwater Heater Relief Valve and Feedwater Heater Outlet Valve. The unit was returned to service on June 9. On June 9 Unit 3 tripped due to a Hi-Hi Steam Generator Water Level condition caused by failure of a feedwater valve controller hand/auto station. Unit 3 was returned to service on June 11. On June 11, during a Turbine Overspeed Trip Test problems associated with the test were noted keeping the Unit off line until June 12. On June 15 Unit 3 was removed from service to repair a leak in a condenser tube. During the process of shutting down Unit 3 the reactor was tripped due to personnel error. Unit 3 returned to service on June 17, 1990.

9008210124 900815
PDR ADOCK 05000250
R PDC

