

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9011080131 DOC. DATE: 90/10/31 NOTARIZED: NO DOCKET #
 FACIL: 50-250 Turkey Point Plant, Unit 3, Florida Power and Light C 05000250
 50-251 Turkey Point Plant, Unit 4, Florida Power and Light C 05000251

AUTH. NAME PLUNKETT, T.F. AUTHOR AFFILIATION Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION Document Control Branch (Document Control Desk)

SUBJECT: Submits implementation status, per GL 83-28, Items 3.2.1 & 3.2.2 re generic implications of Salem ATWS events.

DISTRIBUTION CODE: A055D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR/Licensing Submittal: Salem ATWS Events GL-83-28

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 0	PD2-2 PD	1 1
	EDISON, G	2 2		
INTERNAL:	NRR/DEST/ESB 8D	1 1	NRR/DLPQ/LPEB10	1 0
	NRR/DOEA/OGCB11	1 0	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB 8D	1 0	OC/LFMB	1 0
	OGC/HDS2	1 0	REG-FEE 0.1	1 1
	RES/DSIR/EIB	1 1		
EXTERNAL:	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 15 ENCL 0

MA 4
 web



OCT 31 1990

L-90-380

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: Turkey Point Units 3 and 4
Docket Nos. 50-250 and 50-251
Status of Implementation - Required Actions
Based on Generic Implications of Salem ATWS Events
(Generic Letter 83-28, Items 3.2.1 and 3.2.2)

By letter L-90-95 dated April 5, 1990, Florida Power and Light Company (FPL) provided the implementation status of actions required from Generic Letter (GL) 83-28, for Turkey Point Units 3 and 4. Since issuance of the April 5, 1990 letter, the remaining actions required to comply with the requirements of items 3.2.1 and 3.2.2 have been completed by FPL. A summary of these actions is as follows:

- o Item 3.2.1: FPL has performed a re-review of existing maintenance procedures to ensure that post maintenance testing adequately verifies component capability to perform all required safety functions. The re-review of the above procedures was completed on October 17, 1989.
- o Item 3.2.2: FPL has performed a re-review of test and maintenance procedures to ensure that appropriate vendor and engineering recommendations for testing and maintenance are incorporated. The re-review of the above items was completed on August 1, 1990.

Should there be any additional questions concerning these items, please contact us.

Very truly yours,

T. F. Plunkett
Vice President
Turkey Point Plant Nuclear

TFP/RJT/rjt

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, Turkey Point Plant

9011080131 901031
PDR ADOCK 05000250
P PDC

an FPL Group company

A055
1/0

100 100 100