

Official

SEP 25 1986

Docket No. 50-400
License No. CPPR-158

Carolina Power and Light Company
✓ATTN: Mr. E. E. Utley
Senior Executive Vice President
Power Supply and Engineering
and Construction
P. O. Box 1551
Raleigh, NC 27602

Gentlemen:

SUBJECT: SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE REPORT NO. 50-400/86-56

The NRC Systematic Assessment of Licensee Performance (SALP) Board has completed a special assessment of your Shearon Harris facility in anticipation of your receipt of an operating license. The facility was evaluated for the period of November 1, 1985, through July 31, 1986. The results of the assessment are documented in the enclosed SALP Board Report. The report will be discussed with you at the Region II office on September 30, 1986.

The performance of your Shearon Harris facility was evaluated in the following functional areas: piping systems and supports; auxiliary systems; electrical equipment and cables; instrumentation; quality programs and administrative controls affecting quality (construction); licensing; preoperational testing; operational readiness; radiological controls; fire protection; emergency preparedness; security; training and qualification effectiveness; and quality programs and administrative controls affecting quality (operations). Four functional areas that were evaluated in the previous SALP report were not assessed during this period, primarily due to minimum licensee or inspection activity in the area. Also, six new areas were assessed during this period.

Performance at your Shearon Harris facility was satisfactory, with qualified and experienced personnel directing completion of an effective construction project and conducting the final phases of preoperational testing and operational readiness. Significant strengths were identified in the areas of piping systems and supports, auxiliary systems, licensing, emergency preparedness and security. No major programmatic weaknesses were identified, although a management problem was identified in some areas of the quality programs (construction) and electrical equipment areas. These two areas revealed that when a problem surfaces as an obvious trend, evidence of good feedback information is usually available, but this information is not necessarily acted upon by management to correct the problem in all cases.

8610080017 860925
PDR ADDCK 05000400
Q PDR

IE40
FE01

10/10/52

10/10/52

General
 R. R. Brown
 10/10/52
 10/10/52

The first part of the report deals with the general situation in the country. It is noted that the economy is showing signs of recovery, but that there are still many problems to be solved. The government is working hard to improve the situation, and it is hoped that the people will be able to enjoy a better standard of living in the future.

In the second part of the report, the author discusses the social conditions in the country. It is noted that there is a wide gap between the rich and the poor, and that the poor are often living in very poor conditions. The government is trying to do something about this, but it is not yet clear how successful they will be. It is hoped that the people will be able to enjoy a better standard of living in the future.

The third part of the report deals with the political situation in the country. It is noted that there is a lot of corruption and that the government is not very efficient. The people are often complaining about the government, and it is hoped that they will be able to elect a better government in the future.

RII
J. Mellen
FOR P Fredrickson:jd
9/23/86

RII
D. Verrelli
D Verrelli
9/27/86

RII
K. Walker
K Walker
9/23/86

RII
J. Mellen FOR K. Ban
FOR J Stohr
9/23/86

RII
A. Gibson
A Gibson
9/25/86

RII
M. Ernst
M Ernst
9/25/86

22

SEP 25 1986

Carolina Power and Light Company

2

Your attention is invited to the SALP ratings in each functional area and the fact that the ratings are based on the Board's evaluation of inspections conducted through July 31, 1986. As you are aware there are ongoing inspections in recently identified areas of concern that, had they been completed during the assessment period, could affirm the Board's ratings or, could lead to a possible lower assessment. In this light, you should focus your management attention on those functional areas, where ongoing inspections may reveal a decrease in performance.

Any comments you have concerning our assessment of the performance of your facility should be submitted to this office within 30 days following the date of our meeting. Your comments; a summary of our September 30, 1986 meeting; and my disposition of your comments will be issued as appendices to the enclosed SALP Board Report.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

J. Nelson Grace

J. Nelson Grace
Regional Administrator

Enclosure:
SALP Board Report, Shearon Harris

- cc w/encl:
- ✓ R. A. Watson, Vice President, Harris Nuclear Projects
- ✓ L. Willis, Plant General Manager
Harris Service Lists
- ✓ B. L. Tibbitts, Director of Regulatory Compliance
Harris Service List

- bcc w/encl:
- ✓ C. Barth, ELD
- ✓ J. Moore, ELD
- WRC Resident Inspector
- Document Control Desk
- State of North Carolina

RII	RII	RII	RII	RII	RII
PFredrickson:jd 9/ /86	DVerrelli 9/ /86	RWalker 9/ /86	JStohr 9/ /86	AGibson 9/ /86	MErnst 9/ /86

