

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

MA/2

ACCESSION NBR: 8004170053 DOC. DATE: 80/02/29 NOTARIZED: NO DOCKET #
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400
 50-401 Shearon Harris Nuclear Power Plant, Unit 2, Carolina 05000401
 50-402 Shearon Harris Nuclear Power Plant, Unit 3, Carolina 05000402
 AUTH. NAME AUTHOR AFFILIATION
 CHIANGI, N.J. Carolina Power & Light Co.
 RECIPIENT NAME RECIPIENT AFFILIATION

SUBJECT: Interim deficiency rept re deficiencies in procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads. Estimates corrective action will be completed by 800601.

DISTRIBUTION CODE: B019B COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: -----

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	14 PMMINGR	1	15 BC LWR 3	1
	20 LA LWR 3	1	21 AD LWR	1
INTERNAL:	01 REG FILE	1	02 NRC PDR	1
	05 I&E	2	07 EDO & STAFF	1
	08 MPA	1	09 DEPY DIR DPM	1
	10 QAB	1	11 STANDRDS DEV	1
	13 FIELD COOR/IE	1	16 AD FOR ENGR	1
	17 AD PLANT SYS	1	17 AD REAC SFTY	1
	22 DIR DPM	1	23 OELD	1
	AD/RCI/IE	1	AD/SITE TECH	1
	AEOD	1	DIRECTOR DSE	1
	GEOSCIENCES BR	1	HANAUER, S.	1
	I&C SYS BR	1	MATL ENG BR	1
	MECH ENG BR	1	POWER SYS BR	1
	STRUCT ENG BR	1		
EXTERNAL:	03 LPDR	1	04 NSIC	1
	24 ACRS	16		

LTR
 MOORE
 EPB 2 BC
 KEBLUSEK
 EPB 2 LA

T

APR 21 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 52 ENCL 0

Faint, illegible text at the top of the page, possibly a header or introductory paragraph.

Second section of faint, illegible text, appearing as a distinct paragraph.

A thin horizontal line of faint text separating the upper and lower sections.

Main body of faint, illegible text, consisting of several lines of what appears to be a list or detailed notes.

Bottom section of faint, illegible text, possibly a conclusion or a separate list.



Carolina Power & Light Company

February 29, 1980
MAR 10 8 0:44

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, NW
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT UNITS 1, 2, 3 & 4
DOCKET NOS. 50-400, 50-401, 50-402, 50-403
DEFICIENCIES IN THE PROCUREMENT, FABRICATION, AND
INSPECTION OF ENGINEERED PLATES FOR CONCRETE EMBEDMENT
AND SUPPORT OF SAFETY RELATED LOADS - INTERIM REPORT
(OPEN ITEM 400 & 401/79-14-01, 402 & 403/79-13-01)

Dear Mr. O'Reilly:

Per our December 27, 1979, letter on the subject deficiency, we informed you that approximately 195 plates had been reworked. Twenty plates were still on QA hold pending repair and/or NDT examination and that the the date estimated for completion of corrective action was March 1, 1980. The intent of this letter is to inform you that all corrective action has not yet been completed in that three plates still remain on QA hold pending completion of corrective action involving NDE. Engineering evaluation of several embedded plates remains to be completed. Also, final accountability for all plates needs to be resolved. It is now estimated that all corrective action will be completed by June 1, 1980, at which time the final 10CFR50.55(e) report will be submitted. We will routinely keep you appraised of our progress on this item during your site inspection visits.

If you have any questions regarding this matter, please do not hesitate to contact me.

Yours very truly,

N. J. Chiangi - Manager
Engineering & Construction
Quality Assurance

KVH/bwb

cc: Mr. V. Stello (2)

B019
SE
/10

