

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8011240365 DOC. DATE: 80/11/14 NOTARIZED: NO DOCKET # 05000400  
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000401  
 50-401 Shearon Harris Nuclear Power Plant, Unit 2, Carolina 05000402  
 50-402 Shearon Harris Nuclear Power Plant, Unit 3, Carolina 05000403  
 50-403 Shearon Harris Nuclear Power Plant, Unit 4, Carolina 05000403  
 AUTH. NAME: AUTHOR AFFILIATION  
 CHIANGI, N.J. Carolina Power & Light Co. *mal,*  
 RECIP. NAME: RECIPIENT AFFILIATION  
 O'REILLY, J.P. Region 1, Philadelphia, Office of the Director

SUBJECT: Interim deficiency rept re procurement, fabrication & insp of engineered plates for concrete embedment & support of safety-related loads. Submittal of final rept delayed until 810119, pending completion of investigation.


DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
ACTION:	A/D LICENSNG 04	1		YOUNGBLOOD, B 05	1	
	RUSHBROOK, M. 06	1		WILSON, JERRY 07	1	
INTERNAL:	AD/RCI/IEI 17	1		AEOD 18	1	
	ASLBP/J. HARD	1		D/DIR HUM FAC15	1	
	EDO & STAFF 19	1		EQUIP. QUALI BR11	1	
	HYD/GEO BR 22	1		I&E 09	1	
	LIC. QUALI BR 12	1		MPA 20	1	
	NRC. PDR 02	1		OELD 21	1	
	PROC/TEST REV 13	1		QA BR 14	1	
	<u>REG FILE</u> 01	1		RUTHERFORD, W. IE	1	
STANDRDS DEV 21	1					
EXTERNAL:	ACRS 16	16	1	LPDR 03	1	
	NSIC 08	1				

NOV 25 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 39 ENCL 39





Carolina Power & Light Company  
Raleigh, N. C. 27602

COPY

DISTRIBUTION  
SERVICES UNIT

File: SH N-2/18  
Item 12

1980 NOV 21 AM 9 34

November 14, 1980

US NRC  
DISTRIBUTION SERVICES  
BRANCH

Mr. James P. O'Reilly  
United States Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Northwest  
Atlanta, Georgia 30303

SHEARON HARRIS NUCLEAR POWER PLANT  
UNITS 1, 2, 3 AND 4  
DOCKET NOS. 50-400, 50-401, 50-402 AND 50-403  
DEFICIENCIES IN THE PROCUREMENT,  
FABRICATION AND INSPECTION  
OF ENGINEERED PLATES  
FOR CONCRETE EMBEDMENT AND  
SUPPORT OF SAFETY RELATED  
LOADS - INTERIM REPORT  
OPEN ITEM 400 AND 401/79-14-01,  
402 AND 403/79-13-01

Dear Mr. O'Reilly:

Per our August 29, 1980, interim report on the subject deficiency, we informed you that 22 plates still required some form of corrective action and it was estimated that the corrective action completion date and submittal of final report was November 15, 1980. The intent of this letter is to inform you that submittal of the final report will be delayed due to all investigation not being completed on one plate. Corrective action on 21 out of the 22 plates has been completed and that it is anticipated that the corrective action on the remaining plate will be completed by January 19, 1981, at which time the final 10CFR50.55(e) report will be submitted.

Thank you for your consideration in this matter.

NJC/mt

cc: Mr. V. Stello (2) ✓  
Mr. G. Maxwell

Yours very truly,  
Original Signed By

N. J. Chiangi

N. J. Chiangi - Manager  
Engineering & Construction  
Quality Assurance

B019  
2/10

8011240365

S

1000

1000

1000

NOV 21 1950

COMMUNICATIONS SERVICES  
SECTION

NOV 21 1950

NOV 21 1950

NOV 21 1950

NOV 21 1950

NOV 21 1950

NOV 21 1950

NOV 21 1950

NOV 21 1950

NOV 21 1950

NOV 21 1950

NOV 21 1950

1000

1000