

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8011240388 DOC. DATE: 80/11/14 NOTARIZED: NO DOCKET #
 FACIL: 50-400 Shearon Harris Nuclear Power Plant, Unit 1, Carolina 05000400
 50-401 Shearon Harris Nuclear Power Plant, Unit 2, Carolina 05000401
 50-403 Shearon Harris Nuclear Power Plant, Unit 4, Carolina 05000403
 AUTH. NAME: AUTHOR AFFILIATION: UNIT 3, Carolina 05000402
 CHIANGI, N.J. Carolina Power & Light Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 O'REILLY, J.P. Region 4, Dallas, Office of the Director

MA/1

SUBJECT: Interim deficiency rept re omission of protective coating & existence of damaged coating on containment liner, initially reported on 800917. Application of final coat of paint w/repairs to damaged areas & final rept expected by 810301..


DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES LTR	ENCL
ACTION:	A/D LICENSNG 04	1		YOUNGBLOOD, B 05	1	
	RUSHBROOK, M. 06	1		WILSON, JERRY 07	1	
INTERNAL:	AD/RCI/IE. 17	1		AEOD 18	1	
	ASLBP/J.HARD	1		D/DIR HUM FAC15	1	
	EDO & STAFF 19	1		EQUIP QUALI BR11	1	
	HYD/GEO BR. 22	1		I&E1 09	1	
	LIC QUALI BR 12	1		MPA 20	1	
	NRC PDR. 02	1		OELD 21	1	
	PROG/TEST REV 13	1		QA BR 14	1	
	REG FILE 01	1		RUTHERFORD, N. IE	1	
	STANDRDS DEV 21	1				
EXTERNAL:	ACRS 16	16	1	LPDR 03	1	
	NSIC 08	1				

Nov 25 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 39 ENCL 0



CP&LCarolina Power & Light Company
Raleigh, N. C. 27602DISTRIBUTION
SERVICES UNIT**COPY**

1980 NOV 21 AM 9 34

File: SH N-2/18
Item 49US NRC
DISTRIBUTION SERVICES
BRANCH

November 14, 1980

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest
Atlanta, Georgia 30303SHEARON HARRIS NUCLEAR POWER PLANT
UNITS 1, 2, 3, AND 4
DOCKET NOS. 50-400, 50-401, 50-402, AND 50-403
OMISSION OF PROTECTIVE COATING
AND EXISTENCE OF DAMAGED
COATING ON THE UNIT 1 CONTAINMENT
LINER - INTERIM REPORT

Dear Mr. O'Reilly:

On September 17, 1980, the NRC (Mr. J. K. Rausch) was notified of the subject deficiency as being a potentially reportable item per the provisions of 10CFR50.55(e). On October 17, 1980, the NRC (Mr. J. K. Rausch) was informed that the subject deficiency was considered reportable per the provisions of 10CFR50.55(e).

The deficiency in question pertains to a section of the Unit 1 Containment Liner Plate, adjacent to the refueling canal slab (a two inch gap exists in this area) not having received the final coat of paint, and in some cases, areas of damaged coating not having been repaired. The section in question is approximately five (5) feet in height and sixteen (16) feet long. The intent of this letter is to inform you that corrective action has not been initiated to date since the formwork in this area has not been completely removed, and hence, accessibility is restricted. It is now anticipated that all corrective action will be completed by March 1, 1981, at which time the final 10CFR50.55(e) report will be submitted. When corrective action is implemented, it will consist of application of the final coat of paint and repairs to the damaged areas.

Boia
2/10

S 8011240388

AS OF THE 10 1981

RECEIVED
SERVICES
MAY 11 1981

10-10-81

10-10-81

RECEIVED
SERVICES
MAY 11 1981

RECEIVED
SERVICES
MAY 11 1981

10-10-81

RECEIVED
SERVICES
MAY 11 1981

RECEIVED
SERVICES
MAY 11 1981

RECEIVED
SERVICES
MAY 11 1981

If you have any questions regarding the above, please contact me.

Yours very truly,

Original Signed By

N. J. Chiangi

N. J. Chiangi - Manager
Engineering & Construction
Quality Assurance

NJC/gea (5390)

cc: Mr. G. Maxwell
Mr. V. Stello (2)✓

MEMORANDUM FOR THE RECORD

DATE: 10/10/2010

TO: SAC, NEW YORK

FROM: SA, NEW YORK

SUBJECT: [Illegible]

[Illegible]