

A 8/30/78

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)
DISTRIBUTION FOR INCOMING MATERIAL

50-220

REC: GRIER B H
NRC

ORG: SCHNEIDER R R
NIAGARA MOHAWK PWR

DOCDATE: 08/24/78
DATE RCVD: 08/28/78

DOCTYPE: LETTER NOTARIZED: NO
SUBJECT:

COPIES RECEIVED
LTR 1 ENCL 1

FORWARDING LICENSEE EVENT REPT (RO 50-220/78-030) ON 08/04/78 ~~CONCERNING~~ *after*
~~DURING~~ ROUTINE STARTUP OPERATIONS, 29-03, A MOTOR DRIVEN FEEDWATER PUMP,
WHICH IS A COMPONENT OF THE HPCI SYSTEM, WAS UNAVAILABLE WHILE ITS PUMP SEALS
WERE REPLACED. ~~CONCERNING~~

PLANT NAME: NINE MILE PT -- UNIT 1

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL: *u*

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

INCIDENT REPORTS
(DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#3 BC**W/4 ENCL

INTERNAL:

- REG FILE**W/ENCL
- I & E**W/2 ENCL
- I & C SYSTEMS BR**W/ENCL
- NOVAK/CHECK**W/ENCL
- AD FOR ENG**W/ENCL
- HANAUER**W/ENCL
- AD FOR SYS & PROJ**W/ENCL
- ENGINEERING BR**W/ENCL
- KREGER/J. COLLINS**W/ENCL
- K SEYFRIT/IE**W/ENCL

- NRC PDR**W/ENCL
- MIPC**W/3 ENCL
- EMERGENCY PLAN BR**W/ENCL
- EEB**W/ENCL
- PLANT SYSTEMS BR**W/ENCL
- AD FOR PLANT SYSTEMS**W/ENCL
- REACTOR SAFETY BR**W/ENCL
- VOLLMER/BUNCH**W/ENCL
- POWER SYS BR**W/ENCL

EXTERNAL:

- LPDR'S
- OSWEGO, NY**W/ENCL
- TIC; LIZ CARTER**W/ENCL
- NSIC**W/ENCL
- ACRS CAT B**W/16 ENCL

A704

DISTRIBUTION: LTR 45 ENCL 45
SIZE: 1P+1P+2P

CONTROL NBR: 782370288

***** THE END *****

ccp



100-100

[The body of the document contains extremely faint and illegible text, likely bleed-through from the reverse side of the page. The text is scattered across the page and cannot be transcribed accurately.]

PROBATIONARY DOCKET FILE COPY

NMP-0192

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

August 24, 1978

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1
Technical Specifications, we hereby submit the following Licensee
Event Reports:

- LER 78-30 which is in accordance with Section 6.9.2b(2)
of the Technical Specifications
- LER 78-31 which is in accordance with Section 6.9.2b(2)
of the Technical Specifications
- LER 78-32 which is in accordance with Section 3.1.7a
of the Technical Specifications

These reports were completed in the format designated in
NUREG-0161, dated July 1977.

Very truly yours,

R.R. Schneider
R.R. Schneider
Vice President -
Electric Production

mtm

Attachments (3 each)

xc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

782370288

RECEIVED
REGISTRATION
DIVISION
AUG 24 1978
11 12 02

Aug 24
11 12 02
Hess 70

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | N | M | P | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5
 7 8 | 9 | 14 | 15 | 25 | 26 | 30 | 57 | CAT | 58 | 5
 LICENSEE CODE LICENSE NUMBER LICENSE TYPE 57 CAT 58

CON'T
 0 1 | L | 0 | 5 | 0 | 0 | 0 | 2 | 2 | 0 | 0 | 8 | 0 | 4 | 7 | 8 | 0 | 8 | 2 | 4 | 7 | 8 | 9
 7 8 | 60 | 61 | 68 | 69 | 74 | 75 | 80
 REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During routine startup operations, 29-03, a motor driven feedwater
 0 3 | pump which is a component of the HPCI System, was unavailable while
 0 4 | its pump seals were replaced. T.S. 3.1.8b allows that the HPCI System
 0 5 | is considered operable provided one pump is demonstrated to be
 0 6 | operable and the redundant pump is returned to service within 15 days.
 0 7 | N1-ST-IC5, demonstrated that pump 29-02 was operable. This condition
 0 8 | is reportable per T.S. 6.9.2b(2).

0 9 | SYSTEM CODE: S F (11) CAUSE CODE: X (12) CAUSE SUBCODE: Z (13) COMPONENT CODE: P U M P X X (14) COMP. SUBCODE: B (15) VALVE SUBCODE: Z (16)
 17 | LER/RO REPORT NUMBER: 7 8 (21) EVENT YEAR: 7 8 (22) SEQUENTIAL REPORT NO.: 0 3 0 (24) OCCURRENCE CODE: 0 3 (28) REPORT TYPE: L (30) REVISION NO.: 0 (32)
 ACTION TAKEN: A (18) FUTURE ACTION: Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0 0 0 0 (22) ATTACHMENT SUBMITTED: N (23) NPRO-4 FORM SUB.: N (24) PRIME COMP. SUPPLIER: A (25) COMPONENT MANUFACTURER: W 3 1 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | A Worthington Centrifugal Pump, Model 8WNC141 was removed from service
 1 1 | while routine maintenance was performed on the pump seals. These were
 1 2 | replaced and the pump returned to service with no problems encountered.
 1 3 |
 1 4 |

1 5 | FACILITY STATUS: C (28) % POWER: 0 3 6 (29) OTHER STATUS: NA (30) METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION: Operational Event (32)

1 6 | ACTIVITY CONTENT RELEASED: Z (33) AMOUNT OF ACTIVITY: NA (35) LOCATION OF RELEASE: NA (36)

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION: NA (39)

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 (40) DESCRIPTION: NA (41)

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) DESCRIPTION: NA (43)

2 0 | PUBLICITY ISSUED: N (44) DESCRIPTION: NA (45)

LICENSEE EVENT REPORT

CONTROL BLOCK:

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 7 8 9 N Y N M P 1 1 2 15 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 1 4 5 57 CAT 58

CON'T 0 1 7 8 REPORT SOURCE 60 L 6 0 5 0 0 0 2 2 0 7 0 8 0 8 7 8 8 0 8 2 4 7 8 9 DOCKET NUMBER 68 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 During normal operation, NP02A, a liquid poison pump was unavailable
0 3 while a frozen drain valve was replaced. Three hours later, NP02B
0 4 was unavailable while its drain valve was replaced. T.S. 3.1.2A
0 5 allows operation with only one liquid poison pump for this period of
0 6 time. It is reportable, however, in accordance with T.S. 6.9.2b(2).
0 7 One pump was available at all times, and surveillance tests were per-
0 8 formed as required.

0 9 7 8 9 SYSTEM CODE 9 P C 11 CAUSE CODE 11 X 12 CAUSE SUBCODE 12 Z 13 COMPONENT CODE 13 P U M P X X 14 COMP. SUBCODE 19 E 15 VALVE SUBCODE 20 Z 16
17 LER/RO REPORT NUMBER 21 7 8 22 EVENT YEAR 23 - 24 SEQUENTIAL REPORT NO. 25 0 3 1 26 OCCURRENCE CODE 27 / 28 0 3 29 REPORT TYPE 30 L 31 REVISION NO. 32 0
ACTION TAKEN 33 A 18 FUTURE ACTION 34 Z 19 EFFECT ON PLANT 35 Z 20 SHUTDOWN METHOD 36 Z 21 HOURS 37 0 0 0 0 40 ATTACHMENT SUBMITTED 41 N 23 NRPD-4 FORM SUB. 42 N 24 PRIME COMP. SUPPLIER 43 N 25 COMPONENT MANUFACTURER 44 U 0 5 5 47 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 The Union TD50 Reciprocating Pumps were removed from service while
1 1 their drain valve internals were replaced. These valves had frozen
1 2 closed due to the build-up of boron in them. The condition of the
1 3 drain valves would not have affected the performance of the Liquid
1 4 Poison pumps now degraded the system.

1 5 7 8 9 FACILITY STATUS 9 E 28 % POWER 10 0 9 2 29 OTHER STATUS 30 NA METHOD OF DISCOVERY 45 A 31 DISCOVERY DESCRIPTION 32 Operational Event
1 6 7 8 9 ACTIVITY CONTENT 9 Z 33 RELEASED OF RELEASE 10 Z 34 AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA
1 7 7 8 9 PERSONNEL EXPOSURES 9 0 0 0 37 Z 38 DESCRIPTION 39 NA
1 8 7 8 9 PERSONNEL INJURIES 9 0 0 0 40 DESCRIPTION 41 NA
1 9 7 8 9 LOSS OF OR DAMAGE TO FACILITY 9 Z 42 TYPE 43 NA DESCRIPTION 43
2 0 7 8 9 PUBLICITY 9 N 44 ISSUED DESCRIPTION 45 NA

