ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company Shearon Harris Unit 1 Docket No. 50-400 License No. CPPR-158

The following violation was identified during an inspection conducted on April 20 - May 20, 1985. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50.55(f)(1) requires CP&L to implement the quality assurance program described or referenced in the Preliminary Safety Analysis Report. Section 1.8.5.5 of the CP&L Quality Assurance Program requires that measures be established to insure that inspections are conducted in accordance with documented instructions, procedures, and approved drawings.

Contrary to the above, on May 14, 1985, the inspector identified at least two instances where electrical field modifications were being performed that did not meet the procedural requirements of construction work procedure "Installation of Seismically Supported Electrical Cable Trays, Conduit, Boxes and Bus Ducts" (WP-203). In addition, the Electrical Field Modifications were not documented as a Field Change Request/Permanent Waiver (FCR/PW) within 5 days, as required by this procedure.

This is a Severity Level V violation (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: JUN 0 5 1985

CERTS WELL

Production of the second

ë