

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 7826 Technical Specification Involved 3.11.C.1

Reported Under Technical Specification 6.7.2.b (2)

Date of Occurrence 8/19/78 Time of Occurrence unknown Unit 3
(not logged)

Identification and Description of Occurrence:

Activation of smoke alarm XS-39-93KB without proper cause.

Conditions Prior to Occurrence:

Refueling, outage

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Investigation of the alarm revealed no fire, there is no redundant system.

Apparent Cause of Occurrence:

No apparent cause for the activation was observed.

Analysis of Occurrence:

Normal aging of the detector was believed to be the probable cause of failure.

Corrective Action:

The detector was replaced and tested in accordance with T.S. 4.11.C.1.
Subsequent operation was satisfactory.

Failure Data:

Similar failures: 296/7823, 296/7817, 296/789, 296/7722, 296/7721 and 296/7711.

Faint, illegible markings or text in the top right corner.