



100

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 7912 Technical Specification Involved Table 3.1.A

Reported Under Technical Specification 6.7.2.b(1)

Date of Occurrence 8/15/79 Time of Occurrence _____ Unit _____

Identification and Description of Occurrence:

The setpoint for PS-1-81A, Turbine First Stage Pressure Permissive, was found to exceed the T. S. limit by 8 psig.

Conditions Prior to Occurrence:

Normal Operation.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Setpoint adjusted to within T. S. limits.

Apparent Cause of Occurrence:

Instrument Drift.

Analysis of Occurrence:

None

Corrective Action:

Recalibrated and functionally tested. Performance of 4.1.A.14 will verify other similar switches.

Failure Data:

259/798, 259/7816, 260/7916 and 296/797

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 

