



11 10 15

11 10 15

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 7913 Technical Specification Involved 3.11.B.1

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 8/16/79 Time of Occurrence 10:00 a.m. Unit 3

Identification and Description of Occurrence:

During a core drilling operation in the U-3 diesel generator building a carbon dioxide line was cut.

Conditions Prior to Occurrence:

Normal operation.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

A fire watch was established until repairs were made.

Apparent Cause of Occurrence:

Drawing Error.

Analysis of Occurrence:

The responsible engineer searched the general embedded piping drawings. The pipe involved does not appear on the drawing in the location drilled.

Corrective Action:

Repaired the damaged line. The drawing will be corrected.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 



11