

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912130438 DOC. DATE: 79/11/29 NOTARIZED: NO DOCKET #
 FACIL: 50-259 Browns Ferry Nuclear Power Station, Unit 1, Tennessee 05000259
 50-260 Browns Ferry Nuclear Power Station, Unit 2, Tennessee 05000260
 50-296 Browns Ferry Nuclear Power Station, Unit 3, Tennessee 05000296
 AUTH. NAME: ABERCROMBIE, H.L. AUTHOR AFFILIATION: Tennessee Valley Authority
 RECIP. NAME: RECIPIENT AFFILIATION:

SUBJECT: RO-50-259/79-32: on 791128, during insp of restraints, typical hanger identified as possibly unacceptable. Caused by possible misapplication of hanger. Insp & analyses will be conducted to determine effect on sys.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Incident Reports

NOTES: _____

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	05 BC ORB #3	4				
INTERNAL:	01 REG FILE	1		02 NRC PDR	1	
	09 I&E	2		11 MPA	3	
	14 IA/EDU	1		15 NOVAK/KNIEL	1	
	16 EEB	1		17 AD FOR ENGR	1	
	18 PLANT SYS BR	1		19 I&C SYS BR	1	
	20 AD PLANT SYS	1		22 REAC SAFT BR	1	
	23 ENGR BR	1		24 KREGER	1	
	25 PWR SYS BR	1		26 AD/SITE ANAL	1	
	27 OPERA LIC BR	1		28 ACIDENT ANALYS	1	
	29 AUX SYS BR	1		E JORDAN/IE	1	
	HANAUER, S.	1		STS GROUP LEADR	1	
	TMI-H STREET	1				
EXTERNAL:	03 LPDR	1		04 NSIC	1	
	29 ACRS	16	10			

DEC 17 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 48 ENCL 0

A0/E
4

60

1950

TELECOPY TO NRC
11/29/79

79-8-12-24444
Verify 243-5510

U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

USNRC REGION II
ATLANTA, GEORGIA

79 NOV 29 All : 20

RFEO-50-259/7932

Reported under Technical Specification 6.7.2.a.(9)

Date of occurrence: 11/28/79 Time of occurrence: 2:45 p.m. Units 1, 2, 3

Technical Specification involved: not applicable

Conditions Prior to Occurrence: Restraints were being inspected in accordance with IE Bulletin 79-14. Unit 1 was in normal operation at 1,035 MWe. Unit 2 was in normal operation at 1,095 MWe. Unit 3 was shut down for a refueling outage.

Identification and Description of Occurrence: A typical hanger has been identified that may not be acceptable for its application.

Apparent Cause of Occurrence: Possible misapplication of a typical hanger.

Other Related Events: None

Corrective Action Taken or Planned: Inspections will begin immediately to locate such typical hangers and analysis performed to determine whether or not system function may be affected.

[Handwritten signature]

H. L. Abercrombie
Power Plant Superintendent
Browns Ferry Nuclear Plant

- J. P. O'REILLY
- C. M. UPRIGHT
- P. D. CHENDEMI
- W. B. KENNIS
- E. J. LONG
- R. E. MURPHY
- S. I. SUTHERLAND
- K. H. CLARK

*Lewis
Sibson
Riley*

A002
5
1/0

5 7912130 438